

RAT Observation

- No Observed Source Material (106)
- Possible Source Material (6)
- Source Material Observed (5)



T035 AG - LQ PROPERTIES LLC - 35165 CR 53 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC
Incident Date April 7, 2025
City Galeton, CO
County Weld

Observation

Oiling Observation: 0 No Observable Oil | Id: 535084 | 4/25/2025 1:24:47 PM
(40.510851, -104.565809)
No indication of contamination, taller vegetation





T035 AG - LQ PROPERTIES LLC - 35165 CR 53 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC
Incident Date April 7, 2025
City Galeton, CO
County Weld

Oiling Observation: 0 No Observable Oil | Id: 535383 | 4/25/2025 1:26:26 PM
(40.51091, -104.566473)
Vegetation partially covering soil, no observable impact






T035 AG - LQ PROPERTIES LLC - 35165 CR 53 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC
Incident Date April 7, 2025
City Galeton, CO
County Weld

Oiling Observation: 0 No Observable Oil | Id: 535233 | 4/25/2025 1:32:33 PM
(40.509504, -104.573649)
No product or staining observed





T035 AG - LQ PROPERTIES LLC - 35165 CR 53 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident	Bishop LOC
Incident Date	April 7, 2025
City	Galeton, CO
County	Weld

Oiling Observation: 0 No Observable Oil | Id: 535001 | 4/25/2025 1:48:03 PM
(40.508095, -104.572714)
No signs of contamination





T035 AG - LQ PROPERTIES LLC - 35165 CR 53 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident	Bishop LOC
Incident Date	April 7, 2025
City	Galeton, CO
County	Weld

Oiling Observation: **1 Possible Oil** | Id: 535626 | 4/25/2025 1:17:13 PM
(40.509923, -104.56451)
Some wilted grass.





T035 AG - LQ PROPERTIES LLC - 35165 CR 53 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC
Incident Date April 7, 2025
City Galeton, CO
County Weld

Oiling Observation: **1 Possible Oil** | Id: 535238 | 4/25/2025 1:34:46 PM
(40.508496, -104.574031)

Noticeably stressed vegetation. Yellowing of top leaves.





T035 AG - LQ PROPERTIES LLC - 35165 CR 53 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC
Incident Date April 7, 2025
City Galeton, CO
County Weld

Oiling Observation: **1 Possible Oil** | Id: 535258 | 4/25/2025 1:40:53 PM
(40.508078, -104.574016)

Noticeably stressed vegetation. Yellowing of top leaves.





T035 AG - LQ PROPERTIES LLC - 35165 CR 53 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident	Bishop LOC
Incident Date	April 7, 2025
City	Galeton, CO
County	Weld

Oiling Observation: **1 Possible Oil** | Id: 535110 | 4/25/2025 1:55:50 PM
(40.508129, -104.573457)

Possible signs of contamination (Spotting on leaves)





T035 AG - LQ PROPERTIES LLC - 35165 CR 53 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC
Incident Date April 7, 2025
City Galeton, CO
County Weld

Oiling Observation: **2 Oil Present** | Id: 534998 | 4/25/2025 1:35:57 PM
(40.508116, -104.570166)

Signs of contamination on leaves (light layer of oil and spotting/dying leaves)





T035 AG - LQ PROPERTIES LLC - 35165 CR 53 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident	Bishop LOC
Incident Date	April 7, 2025
City	Galeton, CO
County	Weld

Oiling Observation: **2 Oil Present** | Id: 535007 | 4/25/2025 1:39:39 PM
(40.508088, -104.570403)

Signs of contamination on leaves (light layer of oil and spotting/dying leaves)



Oiling Observation: **2 Oil Present** | Id: 535010 | 4/25/2025 1:41:46 PM
(40.508109, -104.570459)

Signs of contamination on leaves (light layer of oil and spotting/dying leaves)



Oiling Observation: **2 Oil Present** | Id: 535000 | 4/25/2025 1:45:08 PM
(40.508121, -104.570666)

Signs of contamination on leaves (light layer of oil and spotting/dying leaves)

