



RAT Observation

- No Observed Source Material (35)
- Possible Source Material (0)
- Source Material Observed (0)

Observation

Oiling Observation: **0 No Observable Oil** | Id: 541366 | 5/2/2025 7:08:00 AM
(40.506357, -104.604738)
No obvious presence of hydrocarbons on shop east of living quarters



Oiling Observation: 0 No Observable Oil | Id: 541363 | 5/2/2025 1:10:00 PM
(40.506387, -104.605282)
No obvious presence of hydrocarbons on pivot irrigation



Oiling Observation: 0 No Observable Oil | Id: 541360 | 5/2/2025 1:13:00 PM
(40.506386, -104.605255)

No obvious presence of hydrocarbons on propane tank for living quarters and shop area. South side of shop.



Oiling Observation: 0 No Observable Oil | Id: 541359 | 5/2/2025 1:14:19 PM
(40.506393, -104.605232)

3 yard waste management waste container, no obvious presence of hydrocarbons





T155-1 RES - COPELAND ROBERT BARRY - 23760 CR 72 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC
Incident Date April 7, 2025
City Galeton, CO
County Weld

Oiling Observation: 0 No Observable Oil | Id: 541364 | 5/2/2025 1:14:57 PM
(40.506371, -104.605143)
No obvious presence of hydrocarbons



Oiling Observation: 0 No Observable Oil | Id: 541362 | 5/2/2025 1:16:25 PM
(40.506411, -104.605189)

Flag pole north side of shop east side of living quarters, no obvious presence of hydrocarbons





T155-1 RES - COPELAND ROBERT BARRY - 23760 CR 72 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC
Incident Date April 7, 2025
City Galeton, CO
County Weld

Oiling Observation: 0 No Observable Oil | Id: 542462 | 5/2/2025 1:18:24 PM
(40.506413, -104.605364)
No product observed on soil or vegetation or yard plantings





T155-1 RES - COPELAND ROBERT BARRY - 23760 CR 72 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC
Incident Date April 7, 2025
City Galeton, CO
County Weld

Oiling Observation: 0 No Observable Oil | Id: 541405 | 5/2/2025 1:22:45 PM
(40.506808, -104.60445)
No Product



Oiling Observation: 0 No Observable Oil | Id: 541370 | 5/2/2025 1:23:41 PM
(40.506359, -104.604382)

Pivot irrigation sprinkler heads, no obvious presence of hydrocarbons on the sprinkler heads





T155-1 RES - COPELAND ROBERT BARRY - 23760 CR 72 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC
Incident Date April 7, 2025
City Galeton, CO
County Weld

Oiling Observation: 0 No Observable Oil | Id: 541104 | 5/2/2025 1:28:00 PM
(40.506536, -104.604263)
No signs of possible contamination present.



Oiling Observation: 0 No Observable Oil | Id: 541371 | 5/2/2025 1:28:45 PM
(40.506387, -104.605262)

No obvious presence of hydrocarbons on trampoline south side of living quarters



Oiling Observation: 0 No Observable Oil | Id: 541373 | 5/2/2025 1:28:54 PM
(40.506388, -104.605287)

Kids playground south side of the main living area no obvious presence of hydrocarbons.

