




RAT Observation

- No Observed Source Material (4)
- Possible Source Material (0)
- Source Material Observed (0)





T175-2 RES - KARLBERG THOMAS L - 36037 CR 49 WELD  
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC  
Incident Date April 7, 2025  
City Galeton, CO  
County Weld

**Observation**

Oiling Observation: 0 No Observable Oil | Id: 537307 | 4/29/2025 9:20:14 AM  
(40.523292, -104.601985)  
Secondary residence and building.





T175-2 RES - KARLBERG THOMAS L - 36037 CR 49 WELD  
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC  
Incident Date April 7, 2025  
City Galeton, CO  
County Weld

Oiling Observation: 0 No Observable Oil | Id: 538117 | 4/29/2025 9:20:55 AM  
(40.523159, -104.601745)  
No presence of impacted material found at location.





T175-2 RES - KARLBERG THOMAS L - 36037 CR 49 WELD  
Photo Log | Rapid Assessment Technique (RAT)

<b>Incident</b>	Bishop LOC
<b>Incident Date</b>	April 7, 2025
<b>City</b>	Galeton, CO
<b>County</b>	Weld

Oiling Observation: 0 No Observable Oil | Id: 538118 | 4/29/2025 9:24:17 AM  
(40.523342, -104.60177)

No presence of impacted material found at location.





T175-2 RES - KARLBERG THOMAS L - 36037 CR 49 WELD  
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC  
Incident Date April 7, 2025  
City Galeton, CO  
County Weld

Oiling Observation: 0 No Observable Oil | Id: 555156 | 5/23/2025 10:29:05 AM  
(40.523253, -104.601768)  
Propane tank on South end of property

