




RAT Observation

- No Observed Source Material (6)
- Possible Source Material (0)
- Source Material Observed (0)





T158 RES - HACKETT DERECK - 23514 CR 72 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC
Incident Date April 7, 2025
City Galeton, CO
County Weld

Observation

Oiling Observation: 0 No Observable Oil | Id: 539288 | 4/30/2025 3:32:36 PM
(40.507705, -104.610629)
No hydrocarbons detected.

Front garage, Fencing in front main residence.





T158 RES - HACKETT DERECK - 23514 CR 72 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC
Incident Date April 7, 2025
City Galeton, CO
County Weld

Oiling Observation: 0 No Observable Oil | Id: 539287 | 4/30/2025 4:00:45 PM
(40.507342, -104.610768)
No hydrocarbons detected.





T158 RES - HACKETT DERECK - 23514 CR 72 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC
Incident Date April 7, 2025
City Galeton, CO
County Weld

Oiling Observation: 0 No Observable Oil | Id: 539293 | 4/30/2025 4:02:57 PM
(40.506904, -104.610353)
No hydrocarbons detected





T158 RES - HACKETT DERECK - 23514 CR 72 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC
Incident Date April 7, 2025
City Galeton, CO
County Weld

Oiling Observation: 0 No Observable Oil | Id: 539290 | 4/30/2025 4:04:38 PM
(40.506928, -104.610293)
No hydrocarbons detected



Oiling Observation: 0 No Observable Oil | Id: 539294 | 4/30/2025 4:06:17 PM
(40.507112, -104.610198)
No hydrocarbons detected





T158 RES - HACKETT DERECK - 23514 CR 72 WELD
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC
Incident Date April 7, 2025
City Galeton, CO
County Weld

Oiling Observation: 0 No Observable Oil | Id: 539295 | 4/30/2025 4:08:22 PM
(40.507265, -104.609866)
No hydrocarbons detected

