

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404152115

Date Received:  
07/17/2025

**FIR RESOLUTION FORM**

**Overall Status:**

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>TEP</u>		<u>COGCCInspectionReports@terraep.com</u>

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 708303500  
Inspection Date: 02/21/2025 FIR Submit Date: 02/25/2025 FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**LOCATION** - Location ID: 335378

Location Name: PA-66S95W Number: 34NENE County: \_\_\_\_\_  
Qtrqtr: NENE Sec: 34 Twp: 6S Range: 95W Meridian: 6  
Latitude: 39.486689 Longitude: -107.975492

**FACILITY** - API Number: 05-045-00 Facility ID: 335378

Facility Name: PA-66S95W Number: 34NENE  
Qtrqtr: NENE Sec: 34 Twp: 6S Range: 95W Meridian: 6  
Latitude: 39.486689 Longitude: -107.975492

**CORRECTIVE ACTIONS:**

**1** CA# 202702

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 03/13/2025

Response: CA COMPLETED Date of Completion: 03/12/2025

Operator Comment: Cleaned out sediment encroaching production units. Hand seeded cut slope, installed erosion blankets, and used 1 1/2" screen rock to gravel well pad. Corrective Action complete.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

--

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Cleaned out sediment encroaching production units. Hand seeded cut slope, installed erosion blankets, and used 1 1/2" screen rock to gravel well pad. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: \_\_\_\_\_

Title: TEP Representative

Date: 7/17/2025 8:12:46 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>
404152115	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files