





T032 AG - LQ PROPERTIES LLC - 34829 COUNTY ROAD 53
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC
Incident Date April 7, 2025
City Galeton, CO
County Weld

Observation

Oiling Observation: 0 No Observable Oil | Id: 538951 | 4/30/2025 8:36:10 AM
(40.515924, -104.559884)
No indication of contamination.





T032 AG - LQ PROPERTIES LLC - 34829 COUNTY ROAD 53
Photo Log | Rapid Assessment Technique (RAT)

| | |
|----------------------|---------------|
| Incident | Bishop LOC |
| Incident Date | April 7, 2025 |
| City | Galeton, CO |
| County | Weld |

Oiling Observation: 0 No Observable Oil | Id: 539203 | 4/30/2025 8:43:23 AM
(40.515593, -104.55908)
No indication of contamination.





T032 AG - LQ PROPERTIES LLC - 34829 COUNTY ROAD 53
Photo Log | Rapid Assessment Technique (RAT)

| | |
|----------------------|---------------|
| Incident | Bishop LOC |
| Incident Date | April 7, 2025 |
| City | Galeton, CO |
| County | Weld |

Oiling Observation: 0 No Observable Oil | Id: 539542 | 4/30/2025 8:47:33 AM
(40.516717, -104.556365)
No contamination





T032 AG - LQ PROPERTIES LLC - 34829 COUNTY ROAD 53
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC
Incident Date April 7, 2025
City Galeton, CO
County Weld

Oiling Observation: 0 No Observable Oil | Id: 539271 | 4/30/2025 8:49:17 AM
(40.515869, -104.558639)
0 No indication of contamination.





T032 AG - LQ PROPERTIES LLC - 34829 COUNTY ROAD 53
Photo Log | Rapid Assessment Technique (RAT)

| | |
|----------------------|---------------|
| Incident | Bishop LOC |
| Incident Date | April 7, 2025 |
| City | Galeton, CO |
| County | Weld |

Oiling Observation: 0 No Observable Oil | Id: 539192 | 4/30/2025 8:51:27 AM
(40.517104, -104.559215)
No indication of contamination.





T032 AG - LQ PROPERTIES LLC - 34829 COUNTY ROAD 53
Photo Log | Rapid Assessment Technique (RAT)

| | |
|----------------------|---------------|
| Incident | Bishop LOC |
| Incident Date | April 7, 2025 |
| City | Galeton, CO |
| County | Weld |

Oiling Observation: 0 No Observable Oil | Id: 539669 | 4/30/2025 8:54:34 AM
(40.517791, -104.556988)
No contamination





T032 AG - LQ PROPERTIES LLC - 34829 COUNTY ROAD 53
Photo Log | Rapid Assessment Technique (RAT)

| | |
|---------------|---------------|
| Incident | Bishop LOC |
| Incident Date | April 7, 2025 |
| City | Galeton, CO |
| County | Weld |

Oiling Observation: 0 No Observable Oil | Id: 539503 | 4/30/2025 8:55:54 AM
(40.51778, -104.558028)
Dry soil, short/dry brush

No odor, no sheen, no wildlife observed





T032 AG - LQ PROPERTIES LLC - 34829 COUNTY ROAD 53
Photo Log | Rapid Assessment Technique (RAT)

| | |
|----------------------|---------------|
| Incident | Bishop LOC |
| Incident Date | April 7, 2025 |
| City | Galeton, CO |
| County | Weld |

Oiling Observation: 0 No Observable Oil | Id: 539232 | 4/30/2025 8:56:00 AM
(40.517957, -104.557686)

No visible oil staining on topsoil or vegetation.





T032 AG - LQ PROPERTIES LLC - 34829 COUNTY ROAD 53
Photo Log | Rapid Assessment Technique (RAT)

| | |
|----------------------|---------------|
| Incident | Bishop LOC |
| Incident Date | April 7, 2025 |
| City | Galeton, CO |
| County | Weld |

Oiling Observation: 0 No Observable Oil | Id: 539543 | 4/30/2025 8:57:59 AM
(40.518461, -104.556279)
No contamination





T032 AG - LQ PROPERTIES LLC - 34829 COUNTY ROAD 53
Photo Log | Rapid Assessment Technique (RAT)

| | |
|---------------|---------------|
| Incident | Bishop LOC |
| Incident Date | April 7, 2025 |
| City | Galeton, CO |
| County | Weld |

Oiling Observation: 0 No Observable Oil | Id: 539432 | 4/30/2025 8:58:55 AM
(40.518999, -104.555833)

No presence of contamination found. Potential habitat/prairie dog burrows present.

