

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404155583

Date Received:
07/21/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
TEP		COGCCInspectionReports@terraep.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708303560
Inspection Date: 03/06/2025 FIR Submit Date: 03/11/2025 FIR Status:

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335242

Location Name: Federal Number: DOE 1-W-20 County:
Qtrqtr: SWSE Sec: 20 Twp: 6S Range: 95W Meridian: 6
Latitude: 39.504006 Longitude: -108.019092

FACILITY - API Number: 05-045-00 Facility ID: 335242

Facility Name: Federal Number: DOE 1-W-20
Qtrqtr: SWSE Sec: 20 Twp: 6S Range: 95W Meridian: 6
Latitude: 39.504006 Longitude: -108.019092

CORRECTIVE ACTIONS:

1 CA# 203172

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004. Date: 03/26/2025

Response: CA COMPLETED Date of Completion: 03/31/2025

Operator Comment: Location and access road have been bladed/graded to remove rutting. Gravel has been added to increase stabilization. Corrective Action complete.

ECMC Decision: _____

ECMC
Representative:

--

OPERATOR COMMENT AND SUBMITTAL

Comment: Location and access road have been bladed/graded to remove rutting. Gravel has been added to increase stabilization. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: _____

Title: TEP Representative

Date: 7/21/2025 10:58:05 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
------------------------	--------------------

--	--

Total Attach: 0 Files