

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404155611

Date Received:
07/21/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>TEP</u>		<u>COGCCInspectionReports@terraep.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 708303558
Inspection Date: 03/06/2025 FIR Submit Date: 03/11/2025 FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335125

Location Name: Federal Number: PA 11-28 County: _____
Qtrqtr: NWN Sec: 28 Twp: 6S Range: 95W Meridian: 6
W
Latitude: 39.501587 Longitude: -108.011698

FACILITY - API Number: 05-045-00 Facility ID: 335125

Facility Name: Federal Number: PA 11-28
Qtrqtr: NWN Sec: 28 Twp: 6S Range: 95W Meridian: 6
W
Latitude: 39.501587 Longitude: -108.011698

CORRECTIVE ACTIONS:

1 CA# 203171

Corrective Action: Stabilize cut slope. 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 03/26/2025

Response: CA COMPLETED Date of Completion: 03/27/2025

Material was hauled in to re-work cut slope behind units, the disturbed area was hydroseeded, and additional gravel was added to the location to increase stabilization. Corrective Action complete.

Operator _____
Comment: _____

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Material was hauled in to re-work cut slope behind units, the disturbed area was hydroseeded, and additional gravel was added to the location to increase stabilization. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith Signed: _____

Title: TEP Representative Date: 7/21/2025 11:53:28 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404155611	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files