

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/15/2025

Submitted Date:

07/16/2025

Document Number:

714300193**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
Brown, Kari 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Watzman, Ross		rwatzman@kpk.com	All Inspections
Graber, Nikki		nikki.graber@state.co.us	
,		cogcc@kpk.com	All Inspections
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Arthur, Denise		denise.arthur@state.co.us	
Motisi, Dan		dmotisi@kpk.com	KP Kauffman - Environmental Geologist

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
485940	SPILL OR RELEASE	CL			-	Facility 4 @ UPRR 43 PAN AM AE	EI

General Comment:

This is an environmental inspection to determine progress on Spill ID 485940/Remediation Project No 34672. Any corrective actions from previous inspections, NOAVs, or COAs that have not been addressed are still applicable.

There were no operator or contract environmental personnel on location at the time of this field inspection.

Photos attached to document site conditions.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds completely overgrown throughout the location including within and outside of the excavation and on contaminated soil stockpile.		
Corrective Action:	Comply with Rule 606.		Date: 07/23/2025

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type			
Comment:	Orange fencing surrounding the excavation has fallen in some areas. Due to the sensitive nature of this location (residential area), installed orange construction fencing is not adequate to restrict access to the excavation.		
Corrective Action:	Per CA on FIR Doc #710100170, 710100195 & 697602375: "Operator shall implement, continuously monitor and maintain best management practices to protect the environment, public health, safety and welfare and the environment as required by Rule 913.b.(5)B.i and ECMC Guidance 913.b. (5)B i-v which requires fencing used be appropriate to site.		Date: 03/11/2024
Type			
Comment:	Soil stockpile marked 'contaminated' stored on location.		
Corrective Action:	Due to the sensitive nature of this location (residential area), Operator shall install fencing to prevent access to the soil stockpile when site is not attended per Rule 913.b.(5).B.i and Guidance Document Rule 913.b.(5)Bi-v-Remediation Standards.		Date: 07/18/2025

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	485940	Type:	SPILL OR	API Number:	-	Status:	CL	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment: Remedial excavation is open; no additional excavation appears to have been conducted at this location since the previous inspection (Doc No 697602375 – 5/30/2024). Weeds are going on the sidewalls and floor of the open excavation. Floor of the open excavation appeared damp but no groundwater was observed.

Corrective Action: In accordance with 913.d.(1) Operator will investigate impacts to soil, Groundwater, and surface water as soon as the impacts are discovered.

Date: _____

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____

Long _____

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Waste Management:

Type Management Condition GPS (Lat) (Long)

Comment	Soil stockpile marked 'contaminated' stored on location. Stockpile liner is beginning to tear and soil has overflowed berms in some locations; BMPs around the soil stockpile are inadequate. Weeds growing throughout soil stockpile and berms. Soil stockpile in unfenced.				
Corrective Action	Manage waste in compliance with Rule 913.b.iv and COGCC Guidance 913.b.(5)B i-v. Prior to spill/remediation closure Operator will collect soil samples from underneath the observed soil stockpile area and surrounding areas where the stockpile has overflowed berms.				Date: 07/23/2025

Spill/Remediation:

Comment: Quarterly reporting is required for Remediation Project # 34672. Operator is past due on quarterly reporting. The last approved Form 27 was received on March 13, 2024 (Doc # 403694719).

Corrective Action: In accordance with Rule 913.e.(3), Operator will adopt and maintain a quarterly reporting schedule (90 days). Operator will maintain quarterly reporting until the site investigation is complete and the implementation schedule can be updated.

Date: 06/11/2024

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404282615	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7145133
714300194	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7145126