

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

404271663

Date Received:

07/23/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 719500064

Inspection Date: 06/10/2025

FIR Submit Date: 06/11/2025

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 447695

Location Name: BMC B PAD Number: _____ County: _____

Qtrqtr: SWN Sec: 18 Twp: 7S Range: 95W Meridian: 6
W

Latitude: 39.438796 Longitude: -108.046587

FACILITY - API Number: 05-045- -00 Facility ID: 447695

Facility Name: BMC B PAD Number: _____

Qtrqtr: SWN Sec: 18 Twp: 7S Range: 95W Meridian: 6
W

Latitude: 39.438796 Longitude: -108.046587

CORRECTIVE ACTIONS:

1 CA# 205537

Corrective Action: Comply with CECMC pressure safety and general safety rules.

Date: 06/27/2025

Response: CA COMPLETED

Date of Completion: 06/13/2025

Operator
Comment:

Added a 90 and stainless tubing. Corrective Action complete.

ECMC Decision: _____

| | | | |
|----------------------|---|---------------------|-------------------------|
| ECMC Representative: | | | |
| 2 | CA# 205538 | | |
| Corrective Action: | Secure equipment to prevent wildlife entry. | | Date: <u>06/17/2025</u> |
| Response: | CA COMPLETED | Date of Completion: | 06/13/2025 |
| Operator Comment: | Hole in separator has been covered. Corrective Action complete. | | |
| ECMC Decision: | | | |
| ECMC Representative: | | | |

| | |
|---|---|
| OPERATOR COMMENT AND SUBMITTAL | |
| Comment: | CA #205537: Added a 90 and stainless tubing. Corrective Action complete. CA #205538: Hole in separator has been covered. Corrective Action complete. |
| I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete. | |
| Print Name: <u>Jordan Veith</u> | Signed: _____ |
| Title: <u>TEP Representative</u> | Date: <u>7/23/2025 7:37:49 AM</u> |

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|------------------------|--------------------|
| | |

Total Attach: 0 Files