

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404291122

Date Received:
07/23/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10758
Name of Operator: OGRIS OPERATING LLC
Address: PO BOX 53467
City: MIDLAND State: TX Zip: 79710

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>ZECHES. GIENA</u>	<u>719-4970446</u>	<u>gZECHES@ogrisop.com</u>
<u>BACA. DAVE</u>	<u>719-859-4066</u>	<u>dbaca@ogrisop.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 716300910
Inspection Date: 04/28/2025 FIR Submit Date: 04/28/2025 FIR Status: _____

Inspected Operator Information:

Company Name: OGRIS OPERATING LLC Company Number: 10758
Address: PO BOX 53467
City: MIDLAND State: TX Zip: 79710

LOCATION - Location ID: 308408

Location Name: NEW ELK-633S68W Number: 35SESE County: LAS ANIMAS
Qtrqtr: SESE Sec: 35 Twp: 33S Range: 68W Meridian: 6
Latitude: 37.120800 Longitude: -104.960030

FACILITY - API Number: 05-071- -00 Facility ID: 271280

Facility Name: NEW ELK Number: 35-16
Qtrqtr: SESE Sec: 35 Twp: 33S Range: 68W Meridian: 6
Latitude: 37.120800 Longitude: -104.960030

CORRECTIVE ACTIONS:

1 CA# 204444

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002.,(2).D. Date: 05/09/2025

Response: CA COMPLETED Date of Completion: 07/14/2025

Operator Comment: THE IMPACTED SOIL NEAR THE COMPRESSOR HAS BEEN REMOVED AND REPLACED WITH FRESH PAD MATERIAL. THE SKID HAS ALSO BEEN CLEANED. EQUIPMENT MAINTENANCE HAS BEEN PERFORMED AND THE SELF INSPECTION PROCESS REVIEWED.

ECMC Decision: _____

ECMC Representative:

2 CA# 204445

Corrective Action: REMOVE OR IDENTIFY/MARK ALL UNUSED RISERS PER RULE 606.

Date: 05/09/2025

Response: CA COMPLETED

Date of Completion: 07/07/2025

Operator Comment: THE UNUSED RISERS HAVE BEEN REMOVED FROM LOCATION.

ECMC Decision: _____

ECMC Representative:

3 CA# 204446

Corrective Action: DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181.

Date: 04/29/2025

Response: CA COMPLETED

Date of Completion: 07/07/2025

Operator Comment: THE IMPACTED SOIL NEAR THE COMPRESSOR HAS BEEN REMOVED AND REPLACED WITH FRESH PAD MATERIAL. THE SKID HAS ALSO BEEN CLEANED. EQUIPMENT MAINTENANCE HAS BEEN PERFORMED AND THE SELF INSPECTION PROCESS REVIEWED.

ECMC Decision: _____

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: GIENA ZECHES

Signed: _____

Title: ENVIRONMENTAL

Date: 7/23/2025 12:36:43 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404291122	FIR RESOLUTION SUBMITTED
404291128	PHOTO LOG

Total Attach: 2 Files