

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404292036

Date Received:

07/24/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708302381

Inspection Date: 06/27/2024

FIR Submit Date: 07/03/2024

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335627

Location Name: MOBIL-66S95W Number: 8NENW County: _____

Qtrqtr: NENW Sec: 8 Twp: 6S Range: 95W Meridian: 6

Latitude: 39.543372 Longitude: -108.022916

FACILITY - API Number: 05-045-00 Facility ID: 335627

Facility Name: MOBIL-66S95W Number: 8NENW

Qtrqtr: NENW Sec: 8 Twp: 6S Range: 95W Meridian: 6

Latitude: 39.543372 Longitude: -108.022916

CORRECTIVE ACTIONS:

1 CA# 196498

Corrective Action: Secure load line to comply with Rule 608.e.

Date: 07/08/2024

Response: CA COMPLETED

Date of Completion: 10/17/2024

Operator Comment: Load line has been plugged. Corrective Action complete.

ECMC Decision: _____

ECMC
Representative:

2 CA# 196499

Corrective Action: Remove stored equipment to comply with Rule 606.

Date: 07/10/2024

Response: CA COMPLETED

Date of Completion: 10/17/2024

Operator
Comment: Hose has been removed. Corrective Action complete.

ECMC Decision:

ECMC
Representative:

3 CA# 196500

Corrective Action: Cover/protect wellhead cellar.

Date: 08/02/2024

Response: CA COMPLETED

Date of Completion: 10/17/2024

Operator
Comment: Cellar has been covered. Corrective Action complete.

ECMC Decision:

ECMC
Representative:

4 CA# 196501

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 07/18/2024

Response: CA COMPLETED

Date of Completion: 10/17/2024

Operator
Comment: Rill has been repaired. Corrective Action complete.

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA #196498: Load line has been plugged. Corrective Action complete.
CA #196499: Hose has been removed. Corrective Action complete.
CA #196500: Cellar has been covered. Corrective Action complete.
CA #196501: Rill has been repaired. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed:

Title: TEP Representative

Date: 7/24/2025 7:19:23 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404292036	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files