

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404292115

Date Received:  
07/24/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
TEP		COGCCInspectionReports@terraep.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708302684  
Inspection Date: 08/29/2024 FIR Submit Date: 09/04/2024 FIR Status:

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335996

Location Name: AP-66S95W Number: 18NENW County:  
Qtrqtr: NENW Sec: 18 Twp: 6S Range: 95W Meridian: 6  
Latitude: 39.529548 Longitude: -108.042274

FACILITY - API Number: 05-045- -00 Facility ID: 335996

Facility Name: AP-66S95W Number: 18NENW  
Qtrqtr: NENW Sec: 18 Twp: 6S Range: 95W Meridian: 6  
Latitude: 39.529548 Longitude: -108.042274

CORRECTIVE ACTIONS:

1 CA# 198321

Corrective Action: Remove stored supplies to comply with Rule 606. Date: 09/11/2024

Response: CA COMPLETED Date of Completion: 10/17/2024

Operator Comment: Stored supplies have been removed. Corrective Action complete.

ECMC Decision:

ECMC  
Representative:

**2** CA# 198322

Corrective Action: Repair fencing to comply with CECMC General Safety and Housekeeping rules.

Date: 09/18/2024

Response: CA COMPLETED

Date of Completion: 07/07/2025

Operator Comment: Fence has been repaired. Corrective Action complete.

ECMC Decision:

ECMC  
Representative:

**3** CA# 198323

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 07/18/2024

Response: CA COMPLETED

Date of Completion: 10/17/2024

Operator Comment: Access road has been bladed/graded to remove rutting and improve water conveyance to the roadside ditch. Off site rills have been repaired. Sloughing slope behind tank battery has been repaired. Corrective Action complete.

ECMC Decision:

ECMC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: CA #198321: Stored supplies have been removed. Corrective Action complete.  
CA #198322: Fence has been repaired. Corrective Action complete.  
CA #198323: Access road has been bladed/graded to remove rutting and improve water conveyance to the roadside ditch. Off site rills have been repaired. Sloughing slope behind tank battery has been repaired. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed:

Title: TEP Representative

Date: 7/24/2025 9:00:05 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404292115	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files