

# Inspection Photos

**06/05/2025**

**Operator:** FULCRUM ENERGY OPERATING- #10805

**Location ID:** 324749

**Inspection Document #:** 712300161

Jackson County, CO

Logan Maxwell  
Reclamation Specialist  
ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Buffalo Ditch 1-32H Pad  
Location ID: 324749



**Photo 1-4.** Photos taken at the center of the previous Location disturbance, facing north, east, south, and southwest. It is unclear if gravel removal and compaction alleviation has occurred. It is apparent that seeding efforts were conducted.



**Photo 2.** See comments under Photo 1.



Inspection Photos  
Location Name: Buffalo Ditch 1-32H Pad  
Location ID: 324749



**Photo 3.** See comments under Photo 1.



**Photo 4.** See comments under Photo 1.

Inspection Photos  
Location Name: Buffalo Ditch 1-32H Pad  
Location ID: 324749



**Photo 5.** Photo taken at the southwestern portion of the Location, facing south, illustrating vegetation growth, primarily observed sagebrush, Russian Thistle and Brome species.



**Photo 6.** Photo taken of the east portion of the Location, facing east, showing bare areas without vegetation growth.

Inspection Photos  
Location Name: Buffalo Ditch 1-32H Pad  
Location ID: 324749



**Photo 7.** Photo taken illustrating undesirable plant species (e.g., Russian Thistle).



**Photo 8.** Photo taken of the access road, facing north. A portion of the access road to this location and the access road to the Buffalo Ditch 2-32H Location (ID: 324750) remain unreclaimed.

Inspection Photos  
Location Name: Buffalo Ditch 1-32H Pad  
Location ID: 324749



**Photo 9.** Photos 9-10 taken east of the Location, facing east. Photo illustrates the reference area vegetation, primarily sagebrush and rabbitbrush.



**Photo 10.** See comments under Photo 9.

