

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404296712

Date Received:
07/28/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

9 of 9 CAs from the FIR responded to on this Form

9 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10775

Name of Operator: KT RESOURCES LLC

Address: 3381 WESTBROOK LANE

City: HIGHLANDS RANCH State: CO Zip: 80129

Contact Name and Telephone:

Name:

Phone: () Fax: ()

Email:

Additional Operator Contact:

Contact Name	Phone	Email
Gale, Tony	(303) 886-8733	tony@kt-res.com
Adams, Karen	(303) 886-8733	adams@kt-res.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 715501129

Inspection Date: 01/09/2025

FIR Submit Date: 01/09/2025

FIR Status:

Inspected Operator Information:

Company Name: KT RESOURCES LLC

Company Number: 10775

Address: 3381 WESTBROOK LANE

City: HIGHLANDS RANCH State: CO Zip: 80129

LOCATION - Location ID: 316154

Location Name: ANT HILL UNIT-62N96W Number: 30SESW County: RIO BLANCO

Qtrqr: SESW Sec: 30 Twp: 2N Range: 96W Meridian: 6

Latitude: 40.108073 Longitude: -108.209844

FACILITY - API Number: 05-103-00 Facility ID: 232248

Facility Name: ANT HILL UNIT Number: 30-42

Qtrqr: SESW Sec: 30 Twp: 2N Range: 96W Meridian: 6

Latitude: 40.108073 Longitude: -108.209844

CORRECTIVE ACTIONS:

1 CA# 201605

Corrective Action: Install liner material to ensure spill or released materials will be maintained within containment structure.

Date: 02/07/2024

Response: CA COMPLETED

Date of Completion: 02/07/2025

Operator Comment: Welder reinforced metal berm

ECMC Decision: _____

ECMC
Representative:

2 CA# 201606

Corrective Action: Remove and properly dispose of oily waste and stained soils.

Date: 07/05/2023

Response: CA COMPLETED

Date of Completion: 11/01/2024

Operator
Comment:

Oil stains at separator removed and properly disposed of. Treated pump jack stains.

ECMC Decision: _____

ECMC
Representative:

3 CA# 201607

Corrective Action: Repair leaks. Remove and properly dispose of oily waste and stained soils.

Date: 06/29/2023

Response: CA COMPLETED

Date of Completion: 11/01/2024

Operator
Comment:

Removed and properly disposed of stained soils at separator. Treated pump jack stained soil.

ECMC Decision: _____

ECMC
Representative:

4 CA# 201608

Corrective Action: The Tank battery sign will be no less than 3 square feet and no more than 6 square feet, and will provide: Name of the Operator; Telephone number at which the Operator can be reached at all times; Telephone number for local emergency services (911 where available); The public road used to access the Tank battery site; Well name(s) and API number(s) associated with the Tank battery and the legal location of the Well(s); and Location, including the quarter/quarter section, of the Tank battery.

Date: 03/11/2024

Response: CA COMPLETED

Date of Completion: 03/01/2024

Operator
Comment:

All information on the well sign was complete and correct.

ECMC Decision: _____

ECMC
Representative:

5 CA# 201609

Corrective Action: Meters will be calibrated annually unless more frequent calibration is required by contractual obligations or by the Director.

Date: 03/30/2024

Response: CA COMPLETED

Date of Completion: 02/17/2025

Operator
Comment:

Meter found to be defective. Well has been shut in. Meter was replaced July 24, 2025.

ECMC Decision: _____

ECMC
Representative:

6 CA# 201610

Corrective Action: Operators will ensure that container and tank labels are well maintained and legible, and will replace damaged or vandalized labels within 10 days of discovery that the label is no longer legible or is damaged.

Date: 01/20/2025

Response: CA COMPLETED

Date of Completion: 01/09/2025

Operator Comment: Replace sticker on Tanks and Chemical containers

ECMC Decision: _____

ECMC
Representative:

7 CA# 201611

Corrective Action: The Location Entrance sign will identify: The Well name; The Commission's Location identification number (ID #); The Operator's telephone number where it may be reached at all times; and the Telephone number(s) for local emergency services (911 where available).

Date: 03/11/2024

Response: CA COMPLETED

Date of Completion: 03/01/2024

Operator Comment: The information on the tank signs include all data required by the ECMC

ECMC Decision: _____

ECMC
Representative:

8 CA# 201612

Corrective Action: Perform successful mechanical integrity test. If a successful MIT cannot be performed within 30 day CA time the well must be plugged within 3 months.

Date: 02/17/2024

Response: CA COMPLETED

Date of Completion: 04/18/2024

Operator Comment: Alternate MIT approved Doc #403746808

ECMC Decision: _____

ECMC
Representative:

9 CA# 201613

Corrective Action: Provide proper Stormwater BMPs to control runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. Vehicle tracking BMPs to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Date: 06/29/2023

Response: CA COMPLETED

Date of Completion: 02/10/2025

Operator Comment: Located bladed

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Karen Adams

Signed: _____

Title: Prod Admin

Date: 7/28/2025 4:02:39 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
404296712	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files