

## Inspection/Audit Photos

Location: RETAMCO OPERATING INC PHILADELPHIA CREEK 10 PAD

Location ID: 315194

Date: 07/22/2025



Photo # 0474 Entrance to location



Photo # 0476 Location

## Inspection/Audit Photos

Location: RETAMCO OPERATING INC PHILADELPHIA CREEK 10 PAD

Location ID: 315194

Date: 07/22/2025



Photo # 0477 Location Wellhead sign lacks quarter/quarter section information/not in compliance with CECMC rules

Photo # 0480 Location

## Inspection/Audit Photos

Location: RETAMCO OPERATING INC PHILADELPHIA CREEK 10 PAD

Location ID: 315194

Date: 07/22/2025



**Photo # 0504 Unable to locate permit for pit in the CECMC database/not in compliance with CECMC rules**



**Photo # 0513 NW corner of location**

## Inspection/Audit Photos

Location: RETAMCO OPERATING INC PHILADELPHIA CREEK 10 PAD

Location ID: 315194

Date: 07/22/2025



Photo # 0514 SW corner of location



Photo # 0515 SE corner of location

## Inspection/Audit Photos

Location: RETAMCO OPERATING INC PHILADELPHIA CREEK 10 PAD

Location ID: 315194

Date: 07/22/2025



Photo # 0516 NE corner of location



Photo # 0489 PRV vent line does not comply with CECMC pressure safety device rules

## Inspection/Audit Photos

Location: RETAMCO OPERATING INC PHILADELPHIA CREEK 10 PAD

Location ID: 315194

Date: 07/22/2025



**Photo # 0490 Separator housing is damaged and open to wildlife/available for entry by wildlife**



**Photo # 0506 Subsidence on south side of location, additionally is a wildlife hazard/personnel safety hazard**

## Inspection/Audit Photos

Location: RETAMCO OPERATING INC PHILADELPHIA CREEK 10 PAD

Location ID: 315194

Date: 07/22/2025



**Photo # 0508 Subsidence on south side of location,  
additionally is a wildlife hazard/personnel safety hazard**