

## Inspection/Audit Photos

Location: RETAMCO OPERATING INC PHILADELPHIA CREEK 11 PAD

Location ID: 315195

Date: 07/22/2025



Photo # 0523 Entrance to location



Photo # 0524 Location

## Inspection/Audit Photos

Location: RETAMCO OPERATING INC PHILADELPHIA CREEK 11 PAD

Location ID: 315195

Date: 07/22/2025



Photo # 0525 Location



Photo # 0528 Location

## Inspection/Audit Photos

Location: RETAMCO OPERATING INC PHILADELPHIA CREEK 11 PAD

Location ID: 315195

Date: 07/22/2025



Photo # 0571 Location



Photo # 0572 Location

## Inspection/Audit Photos

Location: RETAMCO OPERATING INC PHILADELPHIA CREEK 11 PAD

Location ID: 315195

Date: 07/22/2025



Photo # 0573 Location



Photo # 0575 Location

## Inspection/Audit Photos

Location: RETAMCO OPERATING INC PHILADELPHIA CREEK 11 PAD

Location ID: 315195

Date: 07/22/2025



Photo # 0536 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 0544 It appears that Pit Facility 117171 lat/long is incorrect in the CECMC database/not in compliance with CECMC rules

## Inspection/Audit Photos

Location: RETAMCO OPERATING INC PHILADELPHIA CREEK 11 PAD

Location ID: 315195

Date: 07/22/2025



**Photo # 0549 Failure to minimize erosion & transport of sediment off location/insufficient BMP's**



**Photo # 0553 Failure to minimize erosion & transport of sediment off location/insufficient BMP's**

## Inspection/Audit Photos

Location: RETAMCO OPERATING INC PHILADELPHIA CREEK 11 PAD

Location ID: 315195

Date: 07/22/2025



**Photo # 0555 Failure to minimize erosion & transport of sediment off location/insufficient BMP's**



**Photo # 0557 Failure to minimize erosion & transport of sediment off location/insufficient BMP's**

## Inspection/Audit Photos

Location: RETAMCO OPERATING INC PHILADELPHIA CREEK 11 PAD

Location ID: 315195

Date: 07/22/2025



**Photo # 0559 Failure to minimize erosion & transport of sediment off location/insufficient BMP's**



**Photo # 0562 Failure to minimize erosion & transport of sediment off location/insufficient BMP's**

## Inspection/Audit Photos

Location: RETAMCO OPERATING INC PHILADELPHIA CREEK 11 PAD

Location ID: 315195

Date: 07/22/2025



**Photo # 0564 Failure to minimize erosion & transport of sediment off location/insufficient BMP's**



**Photo # 0565 Debris on location**

## Inspection/Audit Photos

Location: RETAMCO OPERATING INC PHILADELPHIA CREEK 11 PAD

Location ID: 315195

Date: 07/22/2025



Photo # 0566 Debris on location



Photo # 0567 Debris on location

## Inspection/Audit Photos

Location: RETAMCO OPERATING INC PHILADELPHIA CREEK 11 PAD

Location ID: 315195

Date: 07/22/2025



Photo # 0568 Debris on location



Photo # 0581 Unmarked deadman