

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/13/2025

Submitted Date:

07/31/2025

Document Number:

717100274

**FIELD INSPECTION FORM**

Loc ID: 319940 Inspector Name: Rollins, Grace On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**  
 ECMC Operator Number: 31257  
 Name of Operator: FRITZLER RESOURCES INC  
 Address: P O BOX 114  
 City: FORT MORGAN State: CO Zip: 80701

**Findings:**  
 7 Number of Comments  
 4 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Graber, Nikki		nikki.graber@state.co.us	
Fritzler, Gene	(970) 867-9388	gfritzler@bresnan.net	All Inspections
Ahmadian, Alexander		alexander.ahmadian@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201955	WELL	PR	12/01/2024	OW	001-07359	SIMPSON A 9	EI

**General Comment:**  
 ECMC Field Inspection Report Summary  
 This is an environmental inspection. Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.  
  
 Site Name: Simpson #9  
 Wellhead API #: 05-001-07359  
 Date of Inspection: 06/13/2025  
 Weather: Mostly sunny, 88°F  
  
 Site is located within or adjacent to:  
 -Pronghorn Winter Concentration High Priority Habitat  
 -Crop land (immediately adjacent, all directions)  
  
 Current site status:  
 -Stained soil was visible adjacent to the wellhead. A petroleum hydrocarbon odor was observed when the stained soil was disturbed.  
 -Two unmarked containers (buckets, approximately 5 gallons) of unknown petroleum hydrocarbon fluids were observed on location.  
 -Additional unmarked containers (beige spill bucket, blue plastic drum, metal plastic drum) were observed on location.  
 -Trash (black pieces of plastic) was observed on location.  
 -Unused equipment was observed on location.  
 -Pipes were observed on location.  
 -Signage with emergency contact number is visible at the wellhead.  
  
 See attached corrective actions.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	TRASH		
Comment:	Trash (black pieces of plastic) was observed on location.		
Corrective Action:	Comply with Rule 606.	Date:	08/07/2025
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment were observed on location.		
Corrective Action:	Rule 606: Weeds, dead weeds, trash, debris & unnecessary / unused equipment. Within the designated setback (25 feet around any and all equipment), remove trash, & unnecessary / unused equipment, debris and weeds per Rule 606.	Date:	08/15/2025

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 201955 Type: WELL API Number: 001-07359 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: Stained soil was visible adjacent to the wellhead. A petroleum hydrocarbon odor was observed when the stained soil was disturbed.

Corrective Action: Comply with ECMC Rules. Operator shall immediately control and contain spills/releases and investigate, clean up and document impacts per Rule 912.a. Note: for any spills that do not meet the reporting requirements of Rule 912.b.; Operator shall provide documentation of the cleanup efforts (photo documentation and waste disposal manifests) to the Director per Rule 912.a.(5) - Operator may submit documentation via FIRR. Additionally, Operator shall properly handle, transport and dispose of E&P waste in accordance with 905 Series Rules. Date: 08/30/2025

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Waste Management:**

Type	Management	Condition	GPS (Lat) (Long)
Comment	Two unmarked containers (buckets, approximately 5 gallons) of unknown petroleum hydrocarbon fluids were observed on location.		
Corrective Action	Properly store, handle, transport, treat, or dispose of per Rule 906 if Non E&P Waste. Properly dispose of oily waste in accordance with 905.e. if E&P Waste.		Date: <u>08/15/2025</u>

**Spill/Remediation:**

Comment:

Corrective Action:  Date: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment:

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717100280	ECMC Photo Log - Simpson #9 - 06.13.2025	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7169721">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7169721</a>