



Exploration and Production Well P&A Procedure

Wellname **WGV 311-27-697**
Location **NESW 27 6S 97W 6**
Field **NORTH GRAND VALLEY**
County **GARFIELD**
API **05-045-24579**

Prepared By: Brent Antolik
Phone: 570-592-1589

Revision Date:
8/4/2025

ELEV 8387'
Footages 2099 FSL 2169 FWL

Casing: 9-5/8" 36# @ N/A
4-1/2" 11.6# @ N/A

Current Top of Cement: N/A

Purpose: Plug and abandon

Cement Specs: 15.8# Class G, 1.15 ft³/sks, 4.564 gal/sack water mix

Proposed Procedure

- 1 Notified Curtis Haverkamp at ECOM of issue on well
- 2 Freepoint run and detected free at 1,365'
- 3 Ran WL back off charge and backed off fish at 1,365'
- 4 RIH with 1,355' of open-ended 5" 19.5# DP
- 5 TOOH to 3,460'
- 6 Pump 35 bbl fresh water spacer ahead of primary balanced plug cement job
- 7 Pump 41.7 bbl primary slurry - 15.8ppg, 1.16 ft³/ft, 5.000 gal/sk, 202 sx
- 8 Displace w/20 bbl FW to balance plug
- 9 WOC until 500 psi compressive strength is reached
- 10 Top out wellbore until cement returns to surface with 12.3 ppg , 2.31 ft³/sks, 13.17 gal/sack water mix
- 11
- 12
- 13
- 14
- 15
- 16
- 17
- 18
- 19
- 20
- 21
- 22
- 23
- 24
- 25
- 26
- 27
- 28
- 29
- 30
- 31

Dryhole Marker Details

1. Operator: TEP Rocky Mountain LLC
2. Well Name and Number: WGV 311-27-697
3. Surveyed Location: NESW 27 6S 97W 6
4. API Number: 05-045-24579