

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404304584

Date Received:  
08/04/2025

**FIR RESOLUTION FORM**

**Overall Status:**

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 10670  
Name of Operator: BISON IV OPERATING LLC  
Address: 518 17TH STREET SUITE 1800  
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Paul Buck</u>	<u>303-882-5868</u>	<u>pbuck@bisonog.com</u>

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 696307867  
Inspection Date: 07/29/2025 FIR Submit Date: 07/29/2025 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: BISON IV OPERATING LLC Company Number: 10670  
Address: 518 17TH STREET SUITE 1800  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 416477

Location Name: Fox Creek Number: 505-2501H County: \_\_\_\_\_  
Qtrqtr: SESE Sec: 25 Twp: 12N Range: 63W Meridian: 6  
Latitude: \_\_\_\_\_ Longitude: \_\_\_\_\_

FACILITY - API Number: 05-123-00 Facility ID: 481563

Facility Name: Fox Creek 505-2501H Tank Battery Number: \_\_\_\_\_  
Qtrqtr: SESE Sec: 25 Twp: 12N Range: 63W Meridian: 6  
Latitude: \_\_\_\_\_ Longitude: \_\_\_\_\_

CORRECTIVE ACTIONS:

**1** CA# 206532

Corrective Action: For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e." Date: 08/12/2025

Response: CA COMPLETED Date of Completion: 08/01/2025

Operator Comment: The stained soils around the loadout buckets and the north tank have been removed.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

2 CA# 206533

Corrective Action: Comply with Rule 606

Date: 08/12/2025

Response: CA COMPLETED

Date of Completion: 08/01/2025

Operator  
Comment: All unused equipment in the berm has been removed.

ECMC Decision:

ECMC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective actions for stained soil and oil waste, and for unused equipment on site have been performed. Pictures of corrective actions are attached. Bison is unable to attach photographic evidence of the corrective actions and will email them to the inspector directly.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Paul Buck

Signed:

Title: EH&S Manager

Date: 8/4/2025 2:35:41 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

404304584	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files