

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403542919

Date Received:
09/27/2023

FIR RESOLUTION FORM

Overall Status: BOTH

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

- 1 CA Completed
- 1 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10758
 Name of Operator: OGRIS OPERATING LLC
 Address: PO BOX 53467
 City: MIDLAND State: TX Zip: 79710

Contact Name and Telephone:
 Name: _____
 Phone: () _____ Fax: () _____
 Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>WARD, GIENA</u>	<u>719-220-4041</u>	<u>gward@ogrisop.com</u>
<u>BACA, DAVE</u>	<u>719-859-4066</u>	<u>dbaca@ogrisop.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 695108677
 Inspection Date: 09/25/2023 FIR Submit Date: 09/25/2023 FIR Status: _____

Inspected Operator Information:

Company Name: OGRIS OPERATING LLC Company Number: 10758
 Address: PO BOX 53467
 City: MIDLAND State: TX Zip: 79710

LOCATION - Location ID: 333908

Location Name: HILL RANCH-635S67W Number: 3SWSW County: LAS ANIMAS
 Qtrqtr: SWS Sec: 3 Twp: 35S Range: 67W Meridian: 6
W
 Latitude: 37.021200 Longitude: -104.879970

FACILITY - API Number: 05-071-00 Facility ID: 258769

Facility Name: HILL RANCH Number: 03-13R
 Qtrqtr: SWS Sec: 3 Twp: 35S Range: 67W Meridian: 6
W
 Latitude: 37.021200 Longitude: -104.879970

CORRECTIVE ACTIONS:

1 CA# 182077

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition remove and dispose of impacted material per Rule 608.e.

Date: 10/25/2023

Response: CA COMPLETED Date of Completion: 09/26/2023

THE PUMPING UNIT WAS SHUT IN IMMEDIATELY TO STOP FURTHER WATER LEAKS. THE WELLHEAD PACKINGS WERE REPLACED AND THE STUFF BOX WAS SECURELY FASTENED TO STOP THE WATER

Operator Comment: LEAK. THE IMPACTED SOIL NEAR THE WELL HEAD WAS CLEANED UP AND REMOVED FROM LOCATION AND REPLACED WITH FRESH PAD MATERIAL. THE SELF INSPECTION PROCESS HAS BEEN REVIEWED. PLEASE SEE PHOTO LOG FOR DETAILS.

ECMC Decision: Approved pending re-inspection

ECMC Representative:

2 CA# 182078

Corrective Action: FILE REPORTS per Rule 419.b.(5)

Date: 10/25/2023

Response: FACTUAL REVIEW REQUEST

Basis for Review: Requested documentation was submitted prior to the inspection

Operator Comment: Bradenhead testing for both Hill Ranch 03-13V and Hill Ranch 03-13R was completed on 4/20/23 and Form 17s for both were submitted on 4/24/23. Document #s 403382204 & 403382151. Please see attachments for completed field Form 17 bradenhead tests for both locations.

ECMC Decision: Approved pending re-inspection

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CORRECTIVE ACTION COMPLETED. PLEASE SEE PHOTO LOG AND ATTACHED DOCUMENTS.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: GIENA ZECHES

Signed: _____

Title: ENVIRONMENTAL

Date: 9/27/2023 9:28:08 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
403542919	FIR RESOLUTION SUBMITTED
403542932	BRADENHEAD TEST
403542936	BRADENHEAD TEST
403542937	PHOTO LOG

Total Attach: 4 Files