

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404305150

Date Received:
08/05/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-3779

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
ERIN JOSEPH	970-515-1169	ECMCInspections@Oxy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 717900253
Inspection Date: 07/22/2025 FIR Submit Date: 07/24/2025 FIR Status:

Inspected Operator Information:

Company Name: KERR MCGEE OIL & GAS ONSHORE LP Company Number: 47120
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-3779

LOCATION - Location ID: 327554

Location Name: WEBER-63N66W Number: 4NENW County:
Qtrqr: NENW Sec: 4 Twp: 3N Range: 66W Meridian: 6
Latitude: 40.259400 Longitude: -104.784150

FACILITY - API Number: 05-123- -00 Facility ID: 327554

Facility Name: WEBER-63N66W Number: 4NENW
Qtrqr: NENW Sec: 4 Twp: 3N Range: 66W Meridian: 6
Latitude: 40.259400 Longitude: -104.784150

CORRECTIVE ACTIONS:

1 CA# 206513

Corrective Action: Comply with Rules 606 and 1002.f.(2).D. Date: 08/07/2025

Response: CA COMPLETED Date of Completion: 08/04/2025

Operator Comment: The weeds inside the wellhead excavation will be removed accordingly as this excavation is currently in process of ongoing remediation.

ECMC Decision:

ECMC
Representative:

2 CA# 206514

Corrective Action: Rule 913.b(5)B.i. Operators will fence or cover open excavations to prevent access when sites are not attended.

Date: 08/07/2025

Response: CA COMPLETED

Date of Completion: 08/04/2025

Operator
Comment:

The open excavations with groundwater present were fenced off with panels and wildlife screening protection was installed

ECMC Decision:

ECMC
Representative:

3 CA# 206515

Corrective Action: Install wildlife screen per Rule 608.b.(7). If necessary contact CPW and/or USFWS.

Date: 08/07/2025

Response: CA COMPLETED

Date of Completion: 08/04/2025

Operator
Comment:

The open excavations with groundwater present were fenced off with panels and wildlife screening protection was installed

ECMC Decision:

ECMC
Representative:

4 CA# 206516

Corrective Action: Manage waste in compliance with Rule 913.b.iv and ECMC Guidance 913.b.(5)B i-v. Prior to spill/remediation closure Operator will collect soil samples from underneath the observed soil stockpile area..

Date: 08/07/2025

Response: CA COMPLETED

Date of Completion: 08/04/2025

Operator
Comment:

All the soil stockpiles were removed and hauled to a waste disposal facility. Subsequent soil samples were taken beneath the pre-existing piles and we are currently waiting on laboratory analytics of those samples

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: ERIN JOSEPH

Signed: _____

Title: REGULATORY

Date: 8/5/2025 8:25:23 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
404305150	FIR RESOLUTION SUBMITTED
404305171	LOCATION PHOTOS
404305172	LOCATION PHOTOS

Total Attach: 3 Files