

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/29/2025

Submitted Date:

07/31/2025

Document Number:

712300138

FIELD INSPECTION FORM

Loc ID: 458790 Inspector Name: Maxwell, Logan On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10805
Name of Operator: FULCRUM ENERGY OPERATING LLC
Address: 240 SAINT PAUL STREET SUITE 502
City: DENVER State: CO Zip: 80206

Findings:

- 7 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		wes.corliss@fulcrumeo.com	
		inspections@fulcrumeo.com	
		annalee@fulcrumef.com	
		aaron.trujillo@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
458790	LOCATION	AC			-	Oxbow 0880 S29	RI

General Comment:

On 05/29/2025, Northwest Reclamation Specialist Maxwell, EPS Neidel, Environmental Manager Blakeman, and Environmental Supervisor Fisher, conducted a interim reclamation and stormwater management inspection at Fulcrum Energy's Oxbow 0880 S19 Pad in Jackson County, Colorado.

The Location is in the following 1202.d. HPH Density habitat: Greater Sage Grouse Priority Habitat Management and 309.e.1- Greater Sage Grouse undesignated Habitat.

This following compliance issues were observed:

- Good Housekeeping
- Wildlife Protection
- Topsoil Protection

Refer to the "Location" and "Reclamation" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspection that have not been addressed are still applicable. Any new corrective actions without corrective action dates, requires the Operator the comply with the Rules as soon as possible or when environmental conditions permit. Location will remain out of compliance until corrective action(s) has (have) been resolved and a follow up inspection will be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	It was observed in this inspection that weeds (e.g., Russian Thistle) were observed around the perimeter of the Location and on the Topsoil stockpile.		
Corrective Action:	Comply with Rule 606.	Date:	08/08/2025
Type	UNUSED EQUIPMENT		
Comment:	It was observed in this inspection that there was unused equipment/tank on the southeastern portion of the Location.		
Corrective Action:	Comply with Rule 606.a.	Date:	08/08/2025

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#	corrective date
Bird Protectors		
Comment:	It was observed that pipes in the northern portion of the Location have not been properly covered to prevent access by wildlife, including birds and bats. See photos 7-8.	
Corrective Action:	Comply with Rule 902.b.- install covers or other BMPs to prevent wildlife access to equipment.	Date: 08/07/2025

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 458790 Type: LOCATION API Number: - Status: AC Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS In Process

Comment [It was observed in this inspection that the Topsoil stockpile remains sparsely vegetated with predominantly Crested Wheatgrass and Russian Thistle. Install and maintain temporary stabilization until long-term stabilization has occurred. Conduct additional seeding with perennial species until vegetation has established self-sustaining populations.](#)
[Protect the topsoil stockpile from undesirable plant species.](#)

Corrective Action [Comply with Rule 1002.c.](#)

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment It is unclear if all areas not needed for production have been interim reclaimed. A future inspection will determine if additional interim reclamation is needed.

Corrective Action Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

Corrective Action: Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: It was observed in this inspection that here were no stormwater issues observed at this time. Stormwater BMPs appear to be adequately functioning.						Date: _____
Corrective Action: _____						
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404302021	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7170005
712300175	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7169993