

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GR 1-33R Pad

Location ID: 323990



Photo # 8555 From entrance to location

Photo # 8556 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GR 1-33R Pad

Location ID: 323990



Photo # 8557 Location



Photo # 8558 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GR 1-33R Pad

Location ID: 323990



Aug 6, 2025 at 2:06:23 PM
+39.481922,-108.112474

Photo # 8559 Location



Aug 6, 2025 at 2:11:32 PM
+39.482078,-108.112207

Photo # 8560 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GR 1-33R Pad

Location ID: 323990



Photo # 8561 Location



Photo # 8562 Containment near pig station contains unknown fluid & is available for entry by wildlife/wildlife hazard

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GR 1-33R Pad

Location ID: 323990



Photo # 8563 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 8564 PRV vent line does not comply with CECMC pressure safety device rules

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GR 1-33R Pad

Location ID: 323990



Photo # 8565 Open ended load line