

# Inspection Photos

August 6th, 2025

Operator: Hilcorp Energy Company

Location ID: 306764

Inspection Document #: 714002365

La Plata County, CO

Township: NENE 31 34N 10W M

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Argenta 34-10 31-4  
Location ID: 306764

August 6, 2025  
299° NW



LA PLATA COUNTY ROAD 213  
Hilcorp Energy Company  
EMERGENCY CONTACT (505) 324-5170 OR 911  
ARGENTA 34-10 31-4  
LATITUDE 37° 0905.49"  
LONGITUDE 107° 5809.71"  
NENE SEC. 31 T034N R010W  
1240' FNL 1210' FEL  
API NO. 05-067-8719  
ELEV. 6912' DWR # 70903-F  
LA PLATA COUNTY, COLORADO  
FRUITLAND COAL



August 6, 2025  
285° W

LA PLATA COUNTY ROAD 213  
Hilcorp Energy Company  
EMERGENCY CONTACT (505) 324-5170 OR 911  
ARGENTA 34-10 #31-4  
LATITUDE 37° 0905.49"  
LONGITUDE 107° 5809.71"  
NENE SEC. 31 T034N R010W  
1240' FNL 1210' FEL  
API NO. 05-067-8719  
ELEV. 6912' DWR # 70903-F  
LA PLATA COUNTY, COLORADO  
FRUITLAND COAL

BEFORE DIGGING CALL 811

Photo 1. View of the project area taken from the access point facing center.

Inspection Photos

Location Name: Argenta 34-10 31-4

Location ID: 306764



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 2.** Erosion occurring at location access point.

API #: 067-08719

Inspection Photos

Location Name: Argenta 34-10 31-4

Location ID: 306764



August 6, 2025  
162° S



**Photo 3.** Erosion/tunnelling occurring at location access point.

Inspection Photos

Location Name: Argenta 34-10 31-4

Location ID: 306764



**Photo 4.** Erosion occurring at location access point.

Inspection Photos

Location Name: Argenta 34-10 31-4

Location ID: 306764



**Photo 5.** View of drainage adjacent to access road that has not been installed per good engineering practices, BMPs are missing and runoff along the access road drainage is resulting in degradation and incising.