

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404311901

Date Received:
08/13/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:
3 of 3 CAs from the FIR responded to on this Form
3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Kosola, Jason		farmingtonregulatorytechs@hilcorp.com pshorty@hilcorp.com mwalker@hilcorp.com jason.kosola@state.co.us

ECMC INSPECTION SUMMARY:

FIR Document Number: 714002373
Inspection Date: 08/06/2025 FIR Submit Date: 08/08/2025 FIR Status:

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY Company Number: 10133
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 306932

Location Name: UTE 34-10-M34N10W Number: 30SESE County:
Qtrqtr: SESE Sec: 30 Twp: 34N Range: 10W Meridian: M
Latitude: 37.157550 Longitude: -107.969460

FACILITY - API Number: 05-067- -00 Facility ID: 306932

Facility Name: UTE 34-10-M34N10W Number: 30SESE
Qtrqtr: SESE Sec: 30 Twp: 34N Range: 10W Meridian: M
Latitude: 37.157550 Longitude: -107.969460

CORRECTIVE ACTIONS:

1 CA# 206962

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition. Engineer, operate, and maintain equipment within the manufacturer's recommended specifications per Rule 608.e.

Date: 08/09/2025

Response: CA COMPLETED

Date of Completion: 08/11/2025

Operator Comment: The operator tightened and greased the packing on 8/6/25 to stop the stuffing box leak.

ECMC Decision: _____

ECMC Representative: _____

2 CA# 206963

Corrective Action: Report spill or release of E&P waste or produced fluids via form 19 to area EPS Jason Kosola per Rule 912.b.

Date: 08/11/2025

Response: CA COMPLETED

Date of Completion: 08/11/2025

Operator Comment: Spill report was completed but below the 1bbl threshold for agency reporting.

ECMC Decision: _____

ECMC Representative: _____

3 CA# 206964

Corrective Action: Comply with rule 1002 Install or repair required BMPs.

Date: _____

Response: CA COMPLETED

Date of Completion: 08/12/2025

Operator Comment: BMPs have been repaired.

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed: _____

Title: OperationsRegulatory Tech

Date: 8/13/2025 8:21:00 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404314593	UTE 34-10 101R_714002374_Resolved Photos

Total Attach: 1 Files