

ECMC Field Inspection Report Summary

This is an environmental inspection to determine progress on Spill ID 447186 and Remediation Project # 11883. Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Site/Spill Name: MCCALLUM UNIT-610N79W 34NESW

Spill ID: 447186

Remediation Project #: 11883

Well API #:

Flowline Facility ID: 324648

Reported Date of Discovery: 07/28/2016

Date of Inspection: 06/03/2025

Weather: Partly cloudy, 58°F

Site/Spill is located within:

- Greater Sage Grouse Priority Habitat Management Area High Priority Habitat (eastern portion of the spill)
- Pronghorn Migration Corridors High Priority Habitat (fully within)
- Greater Sage Grouse Lek Site High Priority Habitat (fully within)
- Range land (fully within)

Current site status:

- No environmental impacts were visible on the surface of the spill location.
- Signage with emergency contact number is peeling and becoming illegible.
- A sheen was not observed on the water within the well containment.
- A tag on the well reads "Do not operate".

See attached corrective actions.

Location

Overall Good:

Emergency Contact Number:

Comment: Signage with emergency contact number is peeling and becoming illegible.

Corrective Action: Install sign to comply with Rule 605.d.

Date: 09/12/2025

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 447186 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spill/Remediation:

Comment: Remediation Project # 11883 was created to address the ongoing remediation at the MCCALLUM UNIT-610N79W 34NESW location. No environmental impacts were visible on the surface of the spill location. Quarterly reporting is required under Remediation Project # 11883; the last Form 27 for this project was submitted 10/25/2022 (Document # 403205003).

Corrective Action: In accordance with Rule 913.e.(3), Operator will adopt and maintain a quarterly reporting schedule (90 days). Operator shall provide an updated Form 27 for Remediation Project # 11883.

Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717100325	ECMC Photo Log - MCCALLUM UNIT-610N79W 34NESW - 06.03.2025	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7186255