

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/04/2025

Submitted Date:

08/13/2025

Document Number:

717100330

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Rollins, Grace On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 8960
 Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY
 Address: 555 17TH STREET SUITE 3700
 City: DENVER State: CO Zip: 80202

Findings:

- 6 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Watzman, Ross		rwatzman@kpk.com	All Inspections
,		cogcc@kpk.com	All Inspections
Neidel, Kris		kris.neidel@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212158	WELL	PR		OW	057-06051	MCCALLUM UNIT 73	EI
441100	SPILL OR RELEASE	CL	10/30/2018		-	SPILL/RELEASE POINT	EI

General Comment:

ECMC Field Inspection Report Summary

This is an environmental inspection to determine progress on Spill ID 441100 and Remediation Project # 11876. The McCallum Unit 73 well (API # 05-057-06051) was also included in the scope of this inspection. Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Spill Name: McCallum 73 Flowline

Spill ID: 441100

Remediation Project #: 11876

Reported Date of Discovery: 03/12/2015

Well Name: McCallum Unit 73

Well API #: 05-057-06051

Date of Inspection: 06/04/2025

Weather: Mostly sunny, 51°F

Site/Spill is located within or adjacent to:

- Greater Sage Grouse General Habitat Management Area High Priority Habitat
- Pronghorn Migration Corridors High Priority Habitat
- Range land (immediately adjacent, all directions)

Current site status:

- Vegetation within the spill footprint appears limited in comparison to the surrounding field.
- Stained soil was visible adjacent to the well. A strong petroleum hydrocarbon odor was observed when the stained soil was disturbed.
- Weeds are visible adjacent to the well.
- Signage with emergency contact number was visible at the well.

See attached corrective actions.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

WEEDS

Comment: Weeds are visible adjacent to the well.

Corrective Action: Comply with Rule 606.

Date: 08/20/2025

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 212158 Type: WELL API Number: 057-06051 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 441100 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: Stained soil was visible adjacent to the well. A strong petroleum hydrocarbon odor was observed when the stained soil was disturbed.

Corrective Action: Comply with ECMC Rules. Operator shall immediately control and contain spills/releases and investigate, clean up and document impacts per Rule 912.a. Note: for any spills that do not meet the reporting requirements of Rule 912.b.; Operator shall provide documentation of the cleanup efforts (photo documentation and waste disposal manifests) to the Director per Rule 912.a.(5) - Operator may submit documentation via FIRR. Additionally, Operator shall properly handle, transport and dispose of E&P waste in accordance with 905 Series Rules. Date: 09/12/2025

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Spill/Remediation:

Comment: Remediation Project # 11876 was created to address the ongoing remediation at the McCallum 73 Flowline. Vegetation within the spill footprint appears limited in comparison to the surrounding field. Quarterly reporting is required under Remediation Project # 11876; the last Form 27 for this project was submitted 10/27/2022 (Document # 403210015).

Corrective Action: In accordance with Rule 913.e.(3), Operator will adopt and maintain a quarterly reporting schedule (90 days). Operator shall provide an updated Form 27 for Remediation Project # 11876. Date: _____

Emission Control Burner (ECB): _____

Comment:

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717100331	ECMC Photo Log - McCallum 73 Flowline - 06.04.2025	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7186497