

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404315663

Date Received:
08/13/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10805
Name of Operator: FULCRUM ENERGY OPERATING LLC
Address: 240 SAINT PAUL STREET SUITE 502
City: DENVER State: CO Zip: 80206

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
		wes.corliss@fulcrumeo.com
		inspections@fulcrumeo.com
<u>Rikki Ross</u>	<u>970-896-5665</u>	rikki.ross@fulcrumeo.com
		annalee@fulcrumef.com
		aaron.trujillo@state.co.us

ECMC INSPECTION SUMMARY:

FIR Document Number: 712300164
Inspection Date: 06/05/2025 FIR Submit Date: 07/31/2025 FIR Status: _____

Inspected Operator Information:

Company Name: FULCRUM ENERGY OPERATING LLC Company Number: 10805
Address: 240 SAINT PAUL STREET SUITE 502
City: DENVER State: CO Zip: 80206

LOCATION - Location ID: 324750

Location Name: BUFFALO DITCH-67N80W Number: 32SWNE County: _____
Qtrqtr: SWNE Sec: 32 Twp: 7N Range: 80W Meridian: 6
Latitude: 40.534837 Longitude: -106.394970

FACILITY - API Number: 05-057-00 Facility ID: 324750

Facility Name: BUFFALO DITCH-67N80W Number: 32SWNE
Qtrqtr: SWNE Sec: 32 Twp: 7N Range: 80W Meridian: 6
Latitude: 40.534837 Longitude: -106.394970

CORRECTIVE ACTIONS:

1 CA# 206654

Corrective Action: Comply with Rule 606.

Date: 08/08/2025

Response: CA COMPLETED

Date of Completion: 08/07/2025

Operator Comment: Signs and metal sheet have been removed from the location.

ECMC Decision: _____

ECMC Representative: _____

2 CA# 206655

Corrective Action: Comply with Rules 1004.a., 1004.d., and 606.

Date: _____

Response: CA COMPLETED

Date of Completion: 06/26/2025

Operator Comment: The access road identified during the inspection is a ranch road owned by the landowner. The landowner does not wish Fulcrum to reclaim the ranch road. The landowner continues to use this road for personal operation (access the equipment barn, calving barn, calving corral, water well and other important locations on the ranch), as such, Fulcrum has no right to reclaim the road. The location is naturally occurring small gravel which is indigenous to the location. Fulcrum has included multiple photos, from the Buffalo Ditch 1-32H location, 50' east, west, and north of the well pad to demonstrate the naturally occurring small gravel. The original operator did not bring in road base when constructing the pad. 25 gallons of herbicide were sprayed on undesirable plant species on 6/26/26. Fulcrum will continue to monitor weeds and will spray accordingly.

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Rikki Ross

Signed: _____

Title: EHS Field Advisor

Date: 8/13/2025 2:18:02 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
404315663	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files