

H



WELL SITE INSPECTION FORM  
(DRILLING AND PLUGGING)

C

Well Name Ambrose #1 API Number 05 - 087 - 5868  
 Operator Chandler + Simpson Permit # \_\_\_\_\_  
 Location NNNW 6 - 2N - 58W County Morgan  
 Field H Inspector EBB

SCANNED

AL/PA/DA Inspection Results: Well Status:  
 Pass(Y)  Fail(N) \_\_\_\_\_ Date 12/11/91 ND \_\_\_\_\_ DG \_\_\_\_\_ WO \_\_\_\_\_ PR \_\_\_\_\_ SI \_\_\_\_\_ TA \_\_\_\_\_

Date of Inspection Before/During Drilling \_\_\_\_\_

Surf. Csg. Size \_\_\_\_\_ Setting Depth \_\_\_\_\_ Cmt. Vol. \_\_\_\_\_ WOC time \_\_\_\_\_  
 Consistent with APD casing Program? YES \_\_\_\_\_ NO \_\_\_\_\_ Returns \_\_\_\_\_  
 Rig \_\_\_\_\_ BOP'S \_\_\_\_\_ Stage Tool Depth \_\_\_\_\_ Cmt. Vol. \_\_\_\_\_

Date of Inspection Before/During/After Completion \_\_\_\_\_

Prod. Csg. Set? \_\_\_\_\_ Completion Rig/Activity \_\_\_\_\_  
 Drilling Pits: Closed \_\_\_\_\_ Open \_\_\_\_\_ Wellhead Installed: \_\_\_\_\_ Sign: Yes \_\_\_\_\_ No \_\_\_\_\_  
 Tank ID: Yes \_\_\_\_\_ No \_\_\_\_\_ N/A \_\_\_\_\_ Skim Tank/Pit: \_\_\_\_\_ Prod. Tanks: ( ) \_\_\_\_\_ BBLs  
 Equipment \_\_\_\_\_ Meter Run: Yes \_\_\_\_\_ No \_\_\_\_\_  
 Bradenhead Press: \_\_\_\_\_ Fluid: No \_\_\_\_\_ Yes \_\_\_\_\_ Type \_\_\_\_\_ Well Cat. \_\_\_\_\_

AL/PA/DA Inspection

Date Plugged: 83060 Date Permit Expired: \_\_\_\_\_  
 Hole Plugged: Yes  No \_\_\_\_\_ Pits Backfilled: Yes  No \_\_\_\_\_  
 Material Buried: Yes  No \_\_\_\_\_ N/A \_\_\_\_\_ Site Clean: Yes  No \_\_\_\_\_  
 Bond Release OK: Yes  No \_\_\_\_\_ Fed \_\_\_\_\_ Hole Marker: Yes \_\_\_\_\_ No

Date of Safety/Status Inspection \_\_\_\_\_

Comments: \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Violations: Yes \_\_\_\_\_ No \_\_\_\_\_ Notice Sent: Yes \_\_\_\_\_ No \_\_\_\_\_ Date Sent: \_\_\_\_\_