

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/12/2025

Submitted Date:

08/16/2025

Document Number:

717701644

FIELD INSPECTION FORM

Loc ID 331279 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 65110
Name of Operator: O'BRIEN ENERGY RESOURCES CORP
Address: 18 CONGRESS ST STE 207
City: PORTSMOUTH State: NH Zip: 03801

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 8 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Forma, Joe	603-944-8253	joeforma@obenergy.com	All Inspections
Icke, Dean	303-249-2436	Hdpumpingservicesllc@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260833	WELL	TA	07/30/2020	GW	123-20424	LOST CREEK O'BRIEN 3-20	TA

General Comment:

[This is an audit of the scout card and related documents followed by a field audit.](#)

Location

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:	Well sign doesnt reflect well name on the well file. Name should be Lost Creek O'Brien 3-20. See attached photos		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	603-427-2099		
Corrective Action:		Date:	_____

Good Housekeeping:

Type	WEEDS		
Comment:	Overgrown Vegetation around the well needs to be removed for good housekeeping. See attached photos		
Corrective Action:	Comply with Rule 606	Date:	08/25/2025

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No
 Comment: _____
 Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 260833 Type: WELL API Number: 123-20424 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: T/A Form 06A on file

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 10/21/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>ECMC Audit Report Summary</p> <p>On Tuesday, August 12, 2025, at approximately 9:00 AM, Inspector Adam Burns conducted an on-site audit to the following location:</p> <p>Well Name: Lost Creek O'Brien 3-20 Operator: O'Brien Energy Resources Corp API # 05-123-20424 County: Weld</p> <p>During the audit, the following possible compliance issues were identified: Weeds: Overgrown vegetation around the well needs to be removed for good housekeeping. Comply with Rule 606. CA date of 8/25/25 Well sign doesn't reflect well name on the well file. Name should be Lost Creek O'Brien 3-20.</p> <p>A follow-up audit is scheduled to ensure that the compliance issues have been rectified to comply with ECMC rules. Please note that any corrective actions from previous audits that have not been addressed remain applicable.</p>	burnsa	08/16/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717701645	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7191004