

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404287186

Date Received:
08/18/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10464
Name of Operator: CATAMOUNT ENERGY PARTNERS LLC
Address: 600 17TH STREET STE 1400S
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Fischer, Reed</u>	<u>(303) 981-2921</u>	<u>Inspections@catamountep.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 714002295
Inspection Date: 07/10/2025 FIR Submit Date: 07/14/2025 FIR Status: _____

Inspected Operator Information:

Company Name: CATAMOUNT ENERGY PARTNERS LLC Company Number: 10464
Address: 600 17TH STREET STE 1400S
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 438700

Location Name: Carpenter Number: 32-6-3 County: _____
Qtrqtr: NWSE Sec: 3 Twp: 32N Range: 6W Meridian: N
Latitude: 37.045730 Longitude: -107.484670

FACILITY - API Number: 05-067-00 Facility ID: 438700

Facility Name: Carpenter Number: 32-6-3
Qtrqtr: NWSE Sec: 3 Twp: 32N Range: 6W Meridian: N
Latitude: 37.045730 Longitude: -107.484670

CORRECTIVE ACTIONS:

1 CA# 206106

Corrective Action: comply with rule 608, Install or repair wildlife protection equipment. Date: 07/21/2025

Response: CA COMPLETED Date of Completion: 07/15/2025

Operator Comment: Installed wildlife protection equipment

ECMC Decision: _____

ECMC
Representative:

2 CA# 206107

Corrective Action: Spot seeding needs to be conducted within portions of the interim reclamation areas with poor revegetation. Comply with rule 1003.f treat/remove weeds.

Date: _____

Response: CA COMPLETED

Date of Completion: 08/13/2025

Operator
Comment: Removed weeds.

ECMC Decision: _____

ECMC
Representative:

3 CA# 206108

Corrective Action: Storm water BMPs and erosion controls (ie: mulch, hydromulch, straw blankets, etc.) need to be installed and maintained on portions of the project area sparse and bare soils until soils are stabilized with desirable perennial vegetation.

Date: _____

Response: CA COMPLETED

Date of Completion: 08/12/2025

Operator
Comment: Smoothed steep slopes on topsoil storage areas. Seeded and mulched topsoil. Plan to seed again in the fall of 2025.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Nolan Redmond

Signed: _____

Title: Geo/Eng Tech

Date: 8/18/2025 10:54:15 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404287186	FIR RESOLUTION SUBMITTED
404319993	Remedial Report

Total Attach: 2 Files