

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404321501

Date Received:
08/19/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:
2 of 2 CAs from the FIR responded to on this Form
2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10840
Name of Operator: ABUNDANCE ENERGY SERVICES LLC
Address: 2121 S COLUMBIA AVE SUITE 101
City: TULSA State: OK Zip: 74114
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

| Contact Name | Phone | Email |
|--------------|-------|--|
| | | sjbcompliance@abundance-energy.com |
| | | aprice@abundance-energy.com |

ECMC INSPECTION SUMMARY:

FIR Document Number: 714002362
Inspection Date: 08/06/2025 FIR Submit Date: 08/07/2025 FIR Status:

Inspected Operator Information:

Company Name: ABUNDANCE ENERGY SERVICES LLC Company Number: 10840
Address: 2121 S COLUMBIA AVE SUITE 101
City: TULSA State: OK Zip: 74114

LOCATION - Location ID: 325118

Location Name: CRIGLER MVRD UNIT-N33N8W Number: 21NWSE County:
Qtrqr: NWSE Sec: 21 Twp: 33N Range: 8W Meridian: N
Latitude: 37.087290 Longitude: -107.719180

FACILITY - API Number: 05-067-00 Facility ID: 325118

Facility Name: CRIGLER MVRD UNIT-N33N8W Number: 21NWSE
Qtrqr: NWSE Sec: 21 Twp: 33N Range: 8W Meridian: N
Latitude: 37.087290 Longitude: -107.719180

CORRECTIVE ACTIONS:

1 CA# 206946

Corrective Action: Comply with 605, update label to reflect current operator on produced water tank. Date: 08/14/2025

Response: CA COMPLETED Date of Completion: 08/11/2025

Operator Comment: The label on the tank was updated to reflect Abundance Energy.

ECMC Decision: _____

ECMC
Representative:

2 CA# 206947

Corrective Action: Comply with rule 1003, Conduct revegetation/reseeding efforts within portions of the interim reclamation area with bare soils and sparse vegetation.

Date: _____

Response: CA COMPLETED

Date of Completion: 08/14/2025

Operator Comment: Revegetation/reseeding efforts were conducted again on the Northern and Eastern cut slopes of the interim reclamation area on 8/14/2025. Amendments were added to the soil in order to create a suitable seed bed for vegetation growth. Then this area was seeded and blanketed with straw blankets. This will be an uphill battle due to there being little to no vegetation outside of our project area, (On this side of the location) due to poor soil quality. Seed growth is also being restricted by one of the driest years on record.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: See attached for post correction photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jaime Pugh

Signed: _____

Title: Engineering Analyst

Date: 8/19/2025 10:14:51 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|-------------------------------|-----------------------------------|
| 404321513 | Remedial Report with after Photos |

Total Attach: 1 Files