

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404321501

Date Received:  
08/19/2025

**FIR RESOLUTION FORM**

**Overall Status:**

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 10840  
Name of Operator: ABUNDANCE ENERGY SERVICES LLC  
Address: 2121 S COLUMBIA AVE SUITE 101  
City: TULSA State: OK Zip: 74114

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
		<a href="mailto:sjbcompliance@abundance-energy.com">sjbcompliance@abundance-energy.com</a>
		<a href="mailto:aprice@abundance-energy.com">aprice@abundance-energy.com</a>

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 714002362  
Inspection Date: 08/06/2025 FIR Submit Date: 08/07/2025 FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: ABUNDANCE ENERGY SERVICES LLC Company Number: 10840  
Address: 2121 S COLUMBIA AVE SUITE 101  
City: TULSA State: OK Zip: 74114

**LOCATION** - Location ID: 325118

Location Name: CRIGLER MVRD UNIT-N33N8W Number: 21NWSE County: \_\_\_\_\_  
Qtrqr: NWSE Sec: 21 Twp: 33N Range: 8W Meridian: N  
Latitude: 37.087290 Longitude: -107.719180

**FACILITY** - API Number: 05-067-00 Facility ID: 325118

Facility Name: CRIGLER MVRD UNIT-N33N8W Number: 21NWSE  
Qtrqr: NWSE Sec: 21 Twp: 33N Range: 8W Meridian: N  
Latitude: 37.087290 Longitude: -107.719180

**CORRECTIVE ACTIONS:**

**1** CA# 206946

Corrective Action: Comply with 605, update label to reflect current operator on produced water tank. Date: 08/14/2025

Response: CA COMPLETED Date of Completion: 08/11/2025

Operator Comment: The label on the tank was updated to reflect Abundance Energy.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**2** CA# 206947

Corrective Action: Comply with rule 1003, Conduct revegetation/reseeding efforts within portions of the interim reclamation area with bare soils and sparse vegetation.

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 08/14/2025

Operator Comment: Revegetation/reseeding efforts were conducted again on the Northern and Eastern cut slopes of the interim reclamation area on 8/14/2025. Amendments were added to the soil in order to create a suitable seed bed for vegetation growth. Then this area was seeded and blanketed with straw blankets. This will be an uphill battle due to there being little to no vegetation outside of our project area, (On this side of the location) due to poor soil quality. Seed growth is also being restricted by one of the driest years on record.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: See attached for post correction photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jaime Pugh

Signed: \_\_\_\_\_

Title: Engineering Analyst

Date: 8/19/2025 10:14:51 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404321501	FIR RESOLUTION SUBMITTED
404321513	Remedial Report with after Photos

Total Attach: 2 Files