

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/21/2025

Submitted Date:

08/21/2025

Document Number:

717701686

**FIELD INSPECTION FORM**

Loc ID 318605 Inspector Name: Burns, Adam On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Findings:**

- 8 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Silver, Randy		randy.silver@state.co.us	
Revas, Robbie		robbie.revas@state.co.us	
,		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241707	WELL	PR	10/01/2018	OW	123-09496	NORBERT E BADDING 1	PR

**General Comment:**

This is a follow up to prior audit document #717701635. Original audit was for a complaint.  
1 CA appears to have been corrected "mechanical conditions"

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	303-825-4822	Date:	
Corrective Action:			

**Good Housekeeping:**

Type	OTHER		
Comment:	Appears operator placed clean dirt above stained soil as well around the well and needs to be removed for good housekeeping. See attached photos		
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e."	Date:	08/19/2025
Type	OTHER		
Comment:	Stained soil around the well in multiple spots needs to be removed for good housekeeping. See attached photos		
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e."	Date:	08/19/2025

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type: Other	#		corrective date
Comment:	Unmarked Riser needs to be LO/TO and marked. See attached photos		
Corrective Action:	Comply with the 1100 rules	Date:	08/19/2025

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 241707 Type: WELL API Number: 123-09496 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 10/30/2024 Annual Brhd Completed? Yes  
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_  
 End Surf Csg Pressure: 0  
 Comment: \_\_\_\_\_  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p><a href="#">ECMC Audit Report Summary</a></p> <p>On Thursday, August 21, 2025, at approximately 9:27 AM, Inspector Adam Burns conducted an on-site audit to prior audit document #717701635 to the following location:</p> <p>Location: Norbert E Badding-62N68W 22SESE                      Operator: KP Kauffman Company Inc.                      Location ID #318605                      County: Weld</p> <p>1 CA appears to have been corrected. "mechanical conditions"                      During the audit, the following possible compliance issues were identified:                      Stained soil around the well in multiple spots needs to be removed for good housekeeping.                      "Properly dispose of oily waste in accordance with 905.e." CA date of 8/19/25                      Appears operator placed clean dirt above stained soil as well around the well and needs to be removed for good housekeeping. "Properly dispose of oily waste in accordance with 905.e." CA date of 8/19/25                      Unmarked Riser needs to be "LO/TO" and marked. Comply with the 1100 rules. CA date of 8/19/25                      A follow-up audit is scheduled to ensure that the compliance issues have been rectified to comply with ECMC rules.                      Please note that any corrective actions from previous audits that have not been addressed remain applicable.</p>	burnsa	08/21/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717701687	Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7199154">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7199154</a>