

Operator: Highpoint Operating Corp.

Location Name: UPRC FEDERAL-610N64W 23NWNW

Loc ID: 330502

Inspection: 697505940



Exhibit A

CA: Per the previous FIR, the Operator performed soil testing to investigate soil properties related to soil suitability defined in Table 915-1. Soil results indicated that the Operator imported noncompliant topsoil that would not support plant growth. Operator is to remove all non-compliant topsoil and import an approved topsoil source verified by ECMC Reclamation Staff. Once the approved topsoil source has been imported then the Operator shall perform decompaction alleviation, seed with the approved Forest Service seed mix and stabilize the seeded soil. At the time of this inspection, the Operator has stockpiled non-compliant topsoil and are waiting for soil lab results before hauling off the material Operator has failed to complete final reclamation per the due date. Comply with Rule 1004 as described above and submit the required FIRR per Rule 210.b. once final reclamation has been completed.

CA Resolution: Operator has addressed the vegetation issue in order to comply with Rule 1004.