

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/25/2025

Submitted Date:

08/25/2025

Document Number:

716301430

FIELD INSPECTION FORM

Loc ID 309036 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1775 SHERMAN ST. #2775
City: DENVER State: CO Zip: 80203

Findings:

- 10 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
D DYKE, TRACY	719-846-7898	tracy.dyke@enrllc.com	Insp. w/ca's
Distribution, Evergreen	719-846-7898	cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287036	WELL	PR	05/14/2007	CBM	071-09005	BELARDE 12-34	PR

General Comment:

"This is a field audit of the scout card, related documents and the location."

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	PHOTO 4: AREA OF IMPACTED SOIL NEAR COMPRESSOR SKID. PHOTO 5: AREA OF IMPACTED SOIL NEAR COMPRESSOR SKID. PHOTO 6: AREA OF IMPACTED SOIL NEAR PRIME MOVER ENGINE SKID. PHOTO 7: AREA OF IMPACTED SOIL NEAR WELLHEAD.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D.		Date: <u>09/25/2025</u>

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type					corrective date
Type: Vertical Separator	# 1				
Comment:					
Corrective Action:					Date:
Type: Compressor	# 1				
Comment:					
Corrective Action:					Date:
Type: Deadman # & Marked	# 4				
Comment:					
Corrective Action:					Date:
Type: Progressive Cavity	# 1				
Comment:					
Corrective Action:					Date:
Type: Bradenhead	# 1				
Comment:	PHOTO 8: Bradenhead inaccessible.				
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2) THIS IS THE SECOND NOTICE FOR THIS CORRECTIVE ACTION, IMMEDIATE ACTION IS REQUIRED.				Date:
Type: Gas Meter Run	# 1				
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.				
Corrective Action:					Date:
Type: Ancillary equipment	# 1				

Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [PHOTO 9: APPEARS TO BE ANTIFREEZE AND OILY WASTE IN COMPRESSOR SKID.](#)

Corrective Action: **DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. THIS IS THE SECOND NOTICE FOR THIS CORRECTIVE ACTION, IMMEDIATE ACTION IS REQUIRED.**

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary This is a follow up to insp. doc #716301196, CA's have not been addressed and new CA's have been noted in this document. On Tuesday 8-25-2025 at approximately 14:01, I Tom Beardslee Conducted an on-site inspection an Evergreen Natural Resources location BELARDE 12-34 API# 05-071-09005 in Las Animas County Colorado. While there, I observed production operation. During this inspection the following possible compliance issues were observed: PHOTO 4, 5, 6 & 7: AREA OF IMPACTED SOIL NEAR EQUIPMENT ON LOCATION. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002.,(2).D. CA DATE 9-25-2025. PHOTO 8: Bradenhead inaccessible. Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2) THIS IS THE SECOND NOTICE FOR THIS CORRECTIVE ACTION, IMMEDIATE ACTION IS REQUIRED. PHOTO 9: APPEARS TO BE ANTIFREEZE AND OILY WASTE IN COMPRESSOR SKID. DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. THIS IS THE SECOND NOTICE FOR THIS CORRECTIVE ACTION, IMMEDIATE ACTION IS REQUIRED. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	beardslt	08/25/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716301431	INSP. PHOTOS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7203848