

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
08/19/2025
Submitted Date:
08/19/2025
Document Number:
715801386

FIELD INSPECTION FORM

Loc ID 317652 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Operator Information:
ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
12 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239696	WELL	SI	05/01/2021	GW	123-07484	SUCKLA-BROWN UNIT 8	SI

General Comment:
[This is a field audit of the scout card, related documents and the location.](#)

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	the sign is faded, hard to read & needs to be updated.		
Corrective Action:	Install sign to comply with Rule 605.g.		Date: 09/19/2025
Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____
Good Housekeeping:			
Type			
Comment:	Vegetation need to be removed from inside of the well fencing.		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Hof fence		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Wood & metal post with barb wire		
Corrective Action:			Date:
Type	OTHER		
Comment:	fabricated steel pipe around to ancillary equipment.		
Corrective Action:			Date:
Equipment:			
Type: Bradenhead			# 1
Comment:			
Corrective Action:			Date:
Type: Prime Mover			# 1
Comment:			Electric motor
Corrective Action:			Date:
Type: Pump Jack			# 1
Comment:			
Corrective Action:			Date:

Type: Ancillary equipment	# 1	
Comment:	electric panel, meter box & transformers	
Corrective Action:		Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 239696 Type: WELL API Number: 123-07484 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI, the well is part of a 901 Order.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 02/06/2024 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Submit test results to the ECMC.

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Tuesday 8-19-2025 at approximately 1330 hrs. I, Inspector Robbie Revas, Conducted an audit of the well scout card & related forms followed by an onsite inspection: Operator: KP Kauffman Location # 317652 API #05-123-07484 Well name: Suckla-Brown Unit 8 County: Weld Weather: Cloudy & clear Temp: 91* Location: Dry While there, I observed a wellsite & tank battery, SI at the time of inspection. During this inspection the following possible compliance issues were observed: 605.g signs general: CA 9-19-2025. Any corrective actions from previous Inspections that have not been addressed are still applicable See attached photos. A follow up on this site inspection will be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	revasr	08/19/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404322660	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7195162
715801387	Location photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7195153