

# State of Colorado Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404334296

Date Received:  
08/28/2025

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 10736  
Name of Operator: ADVANCED WIRELESS COMMUNICATIONS LLC  
Address: 5500 RAIL RD  
City: FARMINGTON State: NM Zip: 87402

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>KRISTEN</u>	<u>505-608-5253</u>	<u>krysten@advancedwirelessllc.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 700300824  
Inspection Date: 07/14/2025 FIR Submit Date: 07/18/2025 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: ADVANCED WIRELESS COMMUNICATIONS LLC Company Number: 10736  
Address: 5500 RAIL RD  
City: FARMINGTON State: NM Zip: 87402

LOCATION - Location ID: 333801

Location Name: SLUGGER-N33N8W Number: 18NENE County: LA PLATA  
Qtrqtr: NENE Sec: 18 Twp: 33N Range: 8W Meridian: N  
Latitude: 37.107820 Longitude: -107.753990

FACILITY - API Number: 05-067-00 Facility ID: 274482

Facility Name: SLUGGER Number: 1  
Qtrqtr: NENE Sec: 18 Twp: 33N Range: 8W Meridian: N  
Latitude: 37.107820 Longitude: -107.753990

CORRECTIVE ACTIONS:

**1** CA# 206202

Corrective Action: Inspect, maintain and operate Slugger 1 mover, bearing and muffler in good working condition and to manufacturer's specifications to comply with Rule 608.e. Operator should also provide maintenance records, schedules and manufacturer's spec sheets of unit

Date: 07/25/2025

Response: CA COMPLETED Date of Completion: 08/22/2025

Operator Comment: Maintenance Records attached. Review of noise by third party mechanic revealed it is a main bearing that is wearing down. It is an item that wears down over time and can make that noise for several years before it needs immediate attention. However, we will schedule it to be repaired so as not to wait until it fails completely.

ECMC Decision: \_\_\_\_\_

ECMC Representative:

\_\_\_\_\_

**2** CA# 206203

Corrective Action: Connect line or install OOSLAT

Date: 07/23/2025

Response: CA COMPLETED

Date of Completion: 07/23/2025

Operator Comment:

Connected

\_\_\_\_\_

ECMC Decision: \_\_\_\_\_

ECMC Representative:

\_\_\_\_\_

**3** CA# 206204

Corrective Action: Label/mark tank with required information and placard

Date: 08/18/2025

Response: CA COMPLETED

Date of Completion: 07/23/2025

Operator Comment:

Updated with new stickers / labels

\_\_\_\_\_

ECMC Decision: \_\_\_\_\_

ECMC Representative:

\_\_\_\_\_

OPERATOR COMMENT AND SUBMITTAL

Comment:

\_\_\_\_\_

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Krysten Moore

Signed: \_\_\_\_\_

Title: admin

Date: 8/28/2025 9:45:55 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

404334351      Maintenance Records

Total Attach: 1 Files