

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/20/2025

Submitted Date:

08/24/2025

Document Number:

719500368

FIELD INSPECTION FORM

Loc ID 324121 Inspector Name: Morris, Matthew On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

- 9 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		ECMCInspectionReports@flywheelenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257823	WELL	PR	08/08/2000	GW	045-07599	AMERICAN SODA GM 226-35	PR

General Comment:

This is a field audit of the location, scout card, and related documents.

On 8/20/2025 at approximately 12:40, Compliance Inspector Matthew Morris conducted an on-site audit at TEP ROCKY MOUNTAIN LLC, AMERICAN SODA-66S96W/35SWSW at Location ID #324121 in Garfield County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	Battery sign is illegible.		
Corrective Action:	Install sign to comply with CECMC Rules.	Date:	09/25/2025
Type	WELLHEAD		
Comment:	Wellhead sign is illegible.		
Corrective Action:	Install sign to comply with CECMC Rules.	Date:	09/25/2025
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/(970)285-9377

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	TANK BATTERY		
Comment:	Livestock fencing		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Livestock fencing		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Livestock fencing		
Corrective Action:		Date:	

Equipment:

Type:	Horizontal Heated Separator	# 1		corrective date
Comment:				
Corrective Action:			Date:	

Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbls	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 257823 Type: WELL API Number: 045-07599 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						
		Ditches				
		Compaction				
Ditches						
		Check Dams				
Compaction						
Berms						
		Gravel				
		Culverts				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>During the audit, the following compliance issues were observed:</p> <p>1) Battery sign is illegible 2) Wellhead sign is illegible</p> <p>A follow-up on this site audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p>	morris	08/24/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404328055	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7202474
719500369	Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7202473