

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/25/2025

Submitted Date:

08/29/2025

Document Number:

713401029

FIELD INSPECTION FORM

Loc ID: 315098 Inspector Name: Popejoy, Dusty On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10779
Name of Operator: SCOUT ENERGY MANAGEMENT LLC
Address: 13800 MONTFORT DRIVE SUITE 100
City: DALLAS State: TX Zip: 75240

Findings:

- 13 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Rosado, Sydney		Sydney.Rosado@scoutep.com	
Saint, John		jsaint@scoutep.com	
Wiley, Mikel		Mikel.Wiley@scoutep.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Sanford, Anita		anita.sanford@scoutep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230251	WELL	PR	05/01/2018	OW	103-07910	RIGBY A 3X	PR

General Comment:

This is a Field Inspection/audit of the scout card, related documents and the location. This is a Field Inspection/audit of the scout card, related documents and the location.

Location

Lease Road:			
Type	Access		
comment:	Access		
Corrective ActionL		Date:	

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:	970-675-3700/911	
Corrective Action:		Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:	2 unmarked deadman - All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height and not greater than 1 foot east of the guy line anchor.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead valve is accessible/equipped with gauge		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type: Submersible Pump	# 1		
Comment:	ESP		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 230251 Type: WELL API Number: 103-07910 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing well](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention		Chemical tank containment is half full of fluid
		Berms				
Ditches						
Berms	Fail					Damaged Berm/Berm needs maintenance

Comment: 1. Damaged Berm on north side of location/Berm needs maintenance

Corrective Action: Comply with CECMC Stormwater rules

Date: 09/13/2025

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary</p> <p>On 08/25/2025 at approximately 14:36 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection/audit at SCOUT ENERGY MANAGEMENT LLC RIGBY A #3X PAD at Location ID # 315098 in Rio Blanco County, Colorado.</p> <p>This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, Density Habitat regulations.</p> <p>While there, I observed normal production operations.</p> <p>During the inspection/audit, the following compliance issues were observed:</p> <p>1. Stormwater - Damaged Berm on north side of location/Berm needs maintenance with a CA date of 09/13/2025</p> <p>A follow-up on this site inspection/audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p> <p>This is a summary of inspection/audit report.</p>	popejoyd	08/29/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404337001	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7212336
713401030	713401029 Inspection-Audit Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7212332