

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404345512

Date Received:
09/08/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:
4 of 5 CAs from the FIR responded to on this Form
4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Romana Cowden</u>		<u>ecmc.inspections@qb-energy.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 698100309
Inspection Date: 11/20/2024 FIR Submit Date: 11/22/2024 FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC Company Number: 10456
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: _____

Location Name: _____ Number: _____ County: _____
Qtrqtr: SWN Sec: 9 Twp: 2S Range: 97W Meridian: 6
W
Latitude: 39.892642 Longitude: -108.296245

FACILITY - API Number: 05-103-00 Facility ID: 149012

Facility Name: LOVE RANCH CENTRALIZED E&P WASTE Number: _____
Qtrqtr: SWN Sec: 9 Twp: 2S Range: 97W Meridian: 6
W
Latitude: 39.892642 Longitude: -108.296245

CORRECTIVE ACTIONS:

1 CA# 200640

Corrective Action: Remove and properly dispose of oily waste. Comply with Rule 912 for Spills and Releases. Date: 12/22/2024

Response: CA COMPLETED Date of Completion: 07/28/2025

Operator Comment: Staining on the pad surface has been removed remediation will continue at the base and side walls of the pit until compliance is achieved.

ECMC Decision: _____

ECMC Representative: _____

3 CA# 200642

Corrective Action: Comply with pit lining and construction requirements outlined in Rules 907 and 910 prior to reintroducing fluids into the pit.

Date: _____

Response: CA COMPLETED

Date of Completion: 07/28/2025

Operator Comment: The primary liner and secondary bentomat liner have both been fully removed and disposed of at a commercial landfill. Future use of the facility has not been determined. Curnnetly the site is under investigation and remediation phase.

ECMC Decision: _____

ECMC Representative: _____

4 CA# 200643

Corrective Action: Install CPW-approved wildlife exclusion device or netting to prevent access by birds prior to reintroducing fluids into the pit per Rule 1202.a.(4).

Date: _____

Response: CA COMPLETED

Date of Completion: 07/28/2025

Operator Comment: All bird balls have been removed and disposed of at a commercial landfill. The primary liner and secondary bentomat liner have both been fully removed and disposed of at a commercial landfill. Future use of the facility has not been determined. The site is under investigation and remediation phase. No E&P fluids are present at the facility. The fence is still in place to prevent wildlife from entering the facility.

ECMC Decision: _____

ECMC Representative: _____

5 CA# 200644

Corrective Action: Remove and properly dispose of E&P Waste to prevent exposure to wildlife.

Date: 12/31/2024

Response: CA COMPLETED

Date of Completion: 07/28/2025

Operator Comment: Staining on the pad surface has been removed remediation will continue at the base and side walls of the pit until compliance is achieved.

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Romana Cowden

Signed: _____

Title: EHS

Date: 9/8/2025 1:46:23 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
404345512	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files