




**RAT Observation**

- No Observed Source Material (0)
- Possible Source Material (0)
- Source Material Observed (18)



**Observation**

Oiling Observation: **2 Oil Present** | Id: 519580 | 4/19/2025 8:45:05 AM  
(40.506641, -104.582708)

Product present on soil surface and vegetation. Heavy amounts of Product on base of vegetation, browning and yellowing of vegetation, product on rocks





T084 RES - Scott Residence - 34998 CR 51 WELD  
Photo Log | Rapid Assessment Technique (RAT)

<b>Incident</b>	Bishop LOC
<b>Incident Date</b>	April 7, 2025
<b>City</b>	Galeton, CO
<b>County</b>	Weld

Oiling Observation: **2 Oil Present** | Id: 520602 | 4/21/2025 9:05:25 AM  
(40.507635, -104.582526)  
Hydrocarbon presence evident on horse trailer





T084 RES - Scott Residence - 34998 CR 51 WELD  
Photo Log | Rapid Assessment Technique (RAT)

<b>Incident</b>	Bishop LOC
<b>Incident Date</b>	April 7, 2025
<b>City</b>	Galeton, CO
<b>County</b>	Weld

Oiling Observation: **2 Oil Present** | Id: 520596 | 4/21/2025 9:11:55 AM  
(40.507632, -104.582862)  
Hydrocarbon presence evident on corral fencing





T084 RES - Scott Residence - 34998 CR 51 WELD  
Photo Log | Rapid Assessment Technique (RAT)

Incident	Bishop LOC
Incident Date	April 7, 2025
City	Galeton, CO
County	Weld

Oiling Observation: **2 Oil Present** | Id: 520615 | 4/21/2025 9:16:48 AM  
(40.507166, -104.582425)

Hydrocarbon presence evident on debris near box trailers and on box trailer





T084 RES - Scott Residence - 34998 CR 51 WELD  
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC  
Incident Date April 7, 2025  
City Galeton, CO  
County Weld

Oiling Observation: **2 Oil Present** | Id: 520607 | 4/21/2025 9:21:41 AM  
(40.507377, -104.582071)  
Hydrocarbon presence evident on propane tank





T084 RES - Scott Residence - 34998 CR 51 WELD  
Photo Log | Rapid Assessment Technique (RAT)

Incident	Bishop LOC
Incident Date	April 7, 2025
City	Galeton, CO
County	Weld

Oiling Observation: **2 Oil Present** | Id: 520605 | 4/21/2025 9:24:45 AM  
(40.50764, -104.581607)  
Hydrocarbon presence evident on scaffolding beside conex box





T084 RES - Scott Residence - 34998 CR 51 WELD  
Photo Log | Rapid Assessment Technique (RAT)

Incident	Bishop LOC
Incident Date	April 7, 2025
City	Galeton, CO
County	Weld

Oiling Observation: **2 Oil Present** | Id: 520603 | 4/21/2025 9:28:28 AM  
(40.507775, -104.581339)  
Hydrocarbon presence evident on debris beside box trailer





T084 RES - Scott Residence - 34998 CR 51 WELD  
Photo Log | Rapid Assessment Technique (RAT)

Incident	Bishop LOC
Incident Date	April 7, 2025
City	Galeton, CO
County	Weld

Oiling Observation: **2 Oil Present** | Id: 520616 | 4/21/2025 9:36:06 AM  
(40.507545, -104.582161)  
Hydrocarbon presence evident on utility box





T084 RES - Scott Residence - 34998 CR 51 WELD  
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC  
Incident Date April 7, 2025  
City Galeton, CO  
County Weld

Oiling Observation: **2 Oil Present** | Id: 520604 | 4/21/2025 9:39:24 AM  
(40.507453, -104.582282)  
Hydrocarbon presence evident on metal storage shed





T084 RES - Scott Residence - 34998 CR 51 WELD  
Photo Log | Rapid Assessment Technique (RAT)

Incident	Bishop LOC
Incident Date	April 7, 2025
City	Galeton, CO
County	Weld

Oiling Observation: **2 Oil Present** | Id: 520599 | 4/21/2025 9:41:17 AM  
(40.507622, -104.581831)  
Hydrocarbon presence evident on truck on east side of house

