

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/09/2025

Submitted Date:

09/12/2025

Document Number:

710500593

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Sanchez, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments

5 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

ECMC Operator Number: 83130

Name of Operator: STRACHAN EXPLORATION INC

Address: 992 S 4TH AVE SUITE 100-461

City: BRIGHTON State: CO Zip: 80601

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
L, Stacy		stacy@strachanexploration.com	Field inspections
Harms, Jason		Jason@strachanexploration.com	Strachan Exploration
Waggoner, Kyle		kyle.waggoner@state.co.us	
Collins, Kilian		kilian.collins@state.co.us	
Welsh, Brian		brian.welsh@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
448841	GAS GATHERING PIPELINE SYSTEM	AC	11/18/2016		-	LAS ANIMAS PIPELINE	EI

General Comment:

This is an Environmental Inspection for the McClave Gas Compressor Station located in Kiowa County, Colorado.

Facility ID 255965
Flowline system 470744
Spill ID 2608158
Remediation Project # 5701

Location			
Lease Road:			
Type	Access		
comment:			
Corrective ActionL			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Facility placard posted at the entrance to location		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	At the time of inspection, fluids were observed dripping on equipment associated with the Heater Treater.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date: <u>09/26/2025</u>
Type	STORAGE OF SUPL		
Comment:	Compressor yard appears to be used for equipment storage.		
Corrective Action:			Date:
Type	STORAGE OF SUPL		
Comment:	At the time of inspection, a tote with an unknown liquid was stored adjacent to the compressor building. There was evidence of impacts to soils from a leaking valve.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self-inspection processes in accordance with Rule 1102.a. Investigate impacts in accordance with Rule 912.a.		Date: <u>09/26/2025</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
Condensate	WELLHEAD		
Comment:	At the time of inspection, impacts to soils were identified at latitude 38.272935 longitude - 102.816598.		
Corrective Action:	Report spill or release of E&P waste or produced fluids and contact ECMC EPS staff in accordance with Rule 912.b.		Date: <u>09/12/2025</u>
Condensate	Tank		
Comment:	At the time of inspection, a 90-degree elbow on tank piping showed signs of leaking. Impacted soils were present under the elbow.		
Corrective Action:	Control and contain spills/releases and clean in accordance with Rule 912.a. Operator shall determine the extent of impacts to soils and provide photo documentation for cleanup efforts. If impacts meet reporting requirements outlined in Rule 912.b., Operator shall submit a Form 19-I in accordance with Rule 912.b.		Date: <u>09/12/2025</u>

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 448841 Type: GAS API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spill/Remediation:

Comment: This is an Environmental Inspection for Remediation Project # 5701 and Spill/Release Tracking # 2608158. At the time of inspection Remediation Project 5701 remains active with a Conditional Closure for Remediation Project # 5701.

ECMC has evaluated the Conditional Closure, approved in document no. 2231479 dated December 21, 2012. ECMC has determined the Operator of Record, (Strachan Exploration Inc., Operator # 83130), shall submit a Supplemental Form 27-s for Remediation Project # 5701 updated the Operator of Record to reflect Strachan Exploration Inc. in accordance with Rule 913.g. within 30 days from receipt of this Field Inspection. In addition, Operator shall provide an updated implementation schedule for remediation project # 5701 in accordance with 913.d.

Additionally, the Operator shall update and provide Adequacy of Operator's General Liability Insurance and Financial Assurance data field under the Remediation Progress Update tab as required by Rules 703.b. and 705.b.

Any new Sampling and Analysis shall be conducted in accordance with Rule 915.f. Remediations in Progress. For sites that are subject to an open Form 19 or Form 27 as of January 15, 2021, Operators may seek the Director's permission to comply with the version of Table 910-1 that was previously in effect, if Remediation is completed by January 15, 2022. If Remediation at a site subject to an open Form 19 or Form 27 is not completed by January 15, 2022, then the Operator will comply with the current version of Table 915-1.

Corrective Action:	Operator shall submit a Supplemental Form 27 within 30 days from Receipt of this Field Inspection Report	Date: <u>10/13/2025</u>
---------------------------	---	--------------------------------

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500594	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7230280