

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/05/2025

Submitted Date:

09/08/2025

Document Number:

719000619

FIELD INSPECTION FORM

Loc ID 482935 Inspector Name: GARCIA, CHARLES On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96735
 Name of Operator: WILLIFORD RESOURCES LLC
 Address: 6506 S LEWIS AVE STE 102
 City: TULSA State: OK Zip: 74136

Findings:

- 3 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, GENERAL		hwilli@swbell.net	
Labowskie, Steve		steve.labowskie@state.co.us	
,		glennstevens95@gmail.com	

General Comment:

Inspection Report Summary
 On 9/5/25 I Inspector Charles Garcia conducted an on-site inspection.
 Location: 1-33 SWNW M&M TANK BATTERY
 Operator: WILLIFORD RESOURCES LLC
 FACILITY ID#482938
 County: LaPlata

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Horizontal Heated Separator	# 1		corrective date
Comment:	SEPARATOR ON LOCATION APPEARS TO BE OUT OF SERVICE AND IS OPEN ON ONE END WILDLIFE CAN ENTER. ALSO HAS OIL INSIDE LEAKING AND IMPACTING SOIL IF NOT IN USE REMOVE FROM LOCATION SEE LOCATION PICTURES		
Corrective Action:	Install or repair wildlife protection equipment. PER RULE 608.a.(13) Unnecessary equipment COMLPY WITH RULE 606 CLEAN UP IMPACTED SOIL AROUND SEPARATOR rule 1002.f		Date: 09/12/2025

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	OTHER	PBV FIBERGLASS		37.133600,-108.109100
Comment:	OPEN TOP GREEN FIBER GLASS TANK ON LOCATION NEEDS Tank Netting SEE LOCATION PICTURES				
Corrective Action:	Install or repair wildlife protection equipment. PER RULE 608.a.(13)				Date: 09/19/2025

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	<input type="text"/>				
Corrective Action:	<input type="text"/>			Date: <input type="text"/>	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLs	PBV STEEL		37.133500,-108.109400
Comment:	<input type="text"/>				
Corrective Action:	<input type="text"/>				Date: <input type="text"/>

Paint	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404346411	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7224093
719000620	LOCATION PICTURES	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7224090