

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/09/2025

Submitted Date:

09/09/2025

Document Number:

716301494

FIELD INSPECTION FORM

Loc ID 308649 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1775 SHERMAN ST. #2775
City: DENVER State: CO Zip: 80203

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 10 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
D DYKE, TRACY	719-846-7898	tracy.dyke@enrllc.com	Insp. w/ca's
Distribution, Evergreen	719-846-7898	cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277929	WELL	SI	07/10/2013	OBW	071-08398	HARRIER 44-33	SI

General Comment:

"This is a field audit of the scout card, related documents and the location."

Location

Overall Good:

Signs/Marker:

Type			
Comment:	PHOTO 1: WELL SIGN IS ON THE SOUTHSIDE OF THE METER HOUSE WHICH IS VERY CLOSE TO THE SOUTH HIGH BANK OF THE CUT. PER RULE 605 THIS SIGN SHOULD BE PLACED IN AN EASY TO READ FROM A DISTANCE (SHOULD BE ON THE ENTRANCE OF LOCATION SIDE OF METER HOUSE OR AT LEAST THE LOCATION SIDE OF THE METER HOUSE).		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

Good Housekeeping:

Type	WEEDS		
Comment:	PHOTO 3: WEEDS NOT MAINTAIN THROUGHOUT LOCATION.		
Corrective Action:	MAINTAIN WEEDS PER RULE 606.	Date:	10/09/2025

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Type: Bradenhead	# 1		
Comment:	IS ACCESSABLE		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 277929 Type: WELL API Number: 071-08398 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: LAST MIT 12 OF 2024.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 10/21/2011 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: FORM 4 ON FILE

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Culverts	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Tuesday 9-9-2025 at approximately 14:50, I Tom Beardslee Conducted an on-site inspection an Evergreen Natural Resources location HARRIER 44-33 API# 05-071-08398 in Las Animas County Colorado. While there, I observed production operation. During this inspection the following possible compliance issues were observed: PHOTO 1: WELL SIGN IS ON THE SOUTHSIDE OF THE METER HOUSE WHICH IS VERY CLOSE TO THE SOUTH HIGH BANK OF THE CUT. PER RULE 605 THIS SIGN SHOULD BE PLACED IN AN EASY TO READ FROM A DISTANCE (SHOULD BE ON THE ENTRANCE OF LOCATION SIDE OF METER HOUSE OR AT LEAST THE LOCATION SIDE OF THE METER HOUSE). PHOTO 3: WEEDS NOT MAINTAIN THROUGHOUT LOCATION. MAINTAIN WEEDS PER RULE 606. CA DATE 10-9-2025. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	beardslt	09/09/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404347884	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7225401
716301495	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7225386