

Inspection Photos

09/08/2025

Operator: TEP Rocky Mountain LLC #96850

Location ID: 335548

Inspection Doc: 719200183

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335548



Photo 1: Photos showing an overview of the location looking north and south, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335548



Photo 2: Photos showing an overview of the location looking east and west, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335548



Photo 3: Photos showing the western and northern interim areas, respectively. Russian wildrye and rubber rabbitbrush are present on the margins of the interim area, however, cheatgrass and prickly Russian thistle are dominant throughout the interim areas. Interim areas are In Process. Weed management is required.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources



Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335548



Photo 4: Photos showing the northern and northeastern interim areas, respectively. Undesireable plant species, such as kochia and cheatgrass, are present throughout the interim areas. Weed management is required.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335548



Photo 5: Desirable vegetation has established on the cut slope, however, some sediment deposition appears to be present on the working pad surface.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335548



Photo 6: A subsidence appears to be developing at the wellheads. Additional stabilization and recontouring efforts may be required to ensure the working pad surface remains stabilized.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources