

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404361970

Date Received:  
09/22/2025

**FIR RESOLUTION FORM**

**Overall Status:**

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 10705  
Name of Operator: EVERGREEN NATURAL RESOURCES LLC  
Address: 1775 SHERMAN ST. #2775  
City: DENVER State: CO Zip: 80203

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Distribution, Evergreen</u>	<u>719-846-7898</u>	<u>cogcc.evergreen@enrllc.com</u>
<u>D.DYKE, TRACY</u>	<u>719-846-7898</u>	<u>tracy.dyke@enrllc.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 716301430  
Inspection Date: 08/25/2025 FIR Submit Date: 08/25/2025 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: EVERGREEN NATURAL RESOURCES LLC Company Number: 10705  
Address: 1775 SHERMAN ST. #2775  
City: DENVER State: CO Zip: 80203

LOCATION - Location ID: 309036

Location Name: BELARDE-631S66W Number: 34SWNW County: LAS ANIMAS  
Qtrqtr: SWN Sec: 34 Twp: 31S Range: 66W Meridian: 6  
W  
Latitude: 37.305130 Longitude: -104.775490

FACILITY - API Number: 05-071- -00 Facility ID: 287036

Facility Name: BELARDE Number: 12-34  
Qtrqtr: SWN Sec: 34 Twp: 31S Range: 66W Meridian: 6  
W  
Latitude: 37.305130 Longitude: -104.775490

CORRECTIVE ACTIONS:

**1** CA# 207499

Corrective Action: Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2) THIS IS THE SECOND NOTICE FOR THIS CORRECTIVE ACTION, IMMEDIATE ACTION IS REQUIRED.

Date: \_\_\_\_\_

Response: CA COMPLETED Date of Completion: 09/19/2025

Bradenhead exposed per rule 419.a(1), (2)

Operator  
Comment:

ECMC Decision:

ECMC  
Representative:

**2** CA# 207500

Corrective Action:

Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D.

Date: 09/25/2025

Response:

CA COMPLETED

Date of Completion: 09/19/2025

Operator  
Comment:

Stained material removed per rule 1002(2)D

ECMC Decision:

ECMC  
Representative:

**3** CA# 207501

Corrective Action:

DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002.(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. THIS IS THE SECOND NOTICE FOR THIS CORRECTIVE ACTION, IMMEDIATE ACTION IS REQUIRED.

Date: \_\_\_\_\_

Response:

CA COMPLETED

Date of Completion: 09/19/2025

Operator  
Comment:

Skid cleaned per rule 1002(2)D and 1002.f(2)B

ECMC Decision:

ECMC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tracy Dyke

Signed: \_\_\_\_\_

Title: Construction Technician

Date: 9/22/2025 6:41:40 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>
404361970	FIR RESOLUTION SUBMITTED
404361976	Exposed bradenhead

