

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/09/2025

Submitted Date:

09/16/2025

Document Number:

710500604

FIELD INSPECTION FORM

Loc ID 413318 Inspector Name: Sanchez, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10330
Name of Operator: INVESTMENT EQUIPMENT LLC
Address: 558 CASTLE PINES PKWY UNIT B-4
City: CASTLE PINES State: CO Zip: 80108

Findings:

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Bongers, Brent	(361) 935-5633	bbongers@impetroresources.com	
Costa, Ryan		ryan.costa@state.co.us	
Welsh, Brian		brian.welsh@state.co.us	
Waggoner, Kyle		kyle.waggoner@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
413316	WELL	TA	04/01/2021	OW	061-06838	TRADE WINDS 1-28	EI
488284	SPILL OR RELEASE	CL			-	TANK BATTERY	EI
490943	SPILL OR RELEASE	CL	07/16/2025		-	Battery	EI

General Comment:

This is an Environmental Inspection for Spill ID 488284 and Spill ID 490943 located at a tank battery related to the Trade Winds 1-29 well location, located in Kiowa County, Colorado.
API 061-06838
Location ID 413318
Spill ID 488284
Spill ID 490943
Remediation project # 38457

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	Placard located at battery		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	At the time of inspection, a bucket with oily liquids was observed adjacent to plastic tanks located south of the tank battery.		
Corrective Action:	Implement or modify BMPs for improved material handling and spill prevention. Comply with Rule 1002.f.(2)B		Date: <u>09/19/2025</u>

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 413316 Type: WELL API Number: 061-06838 Status: TA Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 488284 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 490943 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spill/Remediation:

Comment: This is an Environmental Inspection for Spill ID 488284, Spill ID 490943, and Remediation Project # 38458.
 At the time of inspection impacted soils were observed within the secondary containment, along containment berms and under the three production tanks within the tank battery location. Spill remediation for Spill ID 488284 and Spill Id 490943 have been transferred to remediation project # 38458. Operator shall fully delineate impacts to soils to determine the full extent of impacts within the remediation area.
 Impacted soils shall be managed in accordance with Rule 905.

Corrective Action: Operator will continue quarterly reporting until the site investigation is complete Date: 09/28/2025
The Next quarterly report is due September 28, 2025

Emission Control Burner (ECB): _____
 Comment: _____
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404356048	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7239006
710500605	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7239005