

Inspected Facilities

Facility ID: 287036 Type: WELL API Number: 071-09005 Status: PR Insp. Status: PR

Producing Well

Comment: THIS IS A FOLLOW UP TO INSP. DOC #716301430 BASED ON PHOTOS SUBMITTED IN FIRR DOC #404361970 NOT ALL CA'S HAVE BEEN ADDRESSED. THE FIRR DOES NOT ADDRESSED THE IMPACTED SOIL CA AT ALL AND ONE OF THE OPERATOR PHOTOS SHOWS IMPACTED SOIL NEAR THE COMPRESSOR SKID. (AGAIN DO NOT SUBMIT INCOMPLETE FIRR'S, ALL CORRECTIVE ACTIONS ON A INSPECTION MUST BE ADDRESSED BEFORE THE FIRR CAN BE SUBMITTED).

Corrective Action: ADDRESS ALL CA'S ON INSP. DOC #716301430 AND SUBMIT A NEW FIRR WITH THE PHOTOS FROM THIS FIRR DOC #404361970 ALONG WITH EVEDENCE THAT THE IMPACTED SOIL HAS BEEN ADDRESSED PER RULES 210.b. & 207.

Date: 09/25/2025

BradenHead

Date of Last Brhd Test: 11/09/2011 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: FORM 4 IS ON FILE

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Tuesday 9-24-2025 at approximately 13:58, I Tom Beardslee Conducted an on-site inspection an Evergreen Natural Resources location BELARDE 12-34</p> <p>API# 05-071-09005 in Las Animas County Colorado. While there, I observed production operation. During this inspection the following possible compliance issues were observed: THIS IS A FOLLOW UP TO INSP. DOC#716301430 BASED ON PHOTOS SUBMITTED IN FIRR DOC #404361970 NOT ALL CA'S HAVE BEEN ADDRESSED. THE FIRR DOES NOT ADDRESSED THE IMPACTED SOIL CA AT ALL AND ONE OF THE OPERATOR PHOTOS SHOWS IMPACTED SOIL NEAR THE COMPRESSOR SKID. ADDRESS ALL CA'S ON INSP. DOC #716301430 AND SUBMIT A NEW FIRR WITH THE PHOTOS FROM THIS FIRR DOC #404361970 ALONG WITH EVEDENCE THAT THE IMPACTED SOIL HAS BEEN ADDRESSED PER RULES 210.b. & 207. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	beardslt	09/24/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716301560	OPERATOR PHOTOS W/ IMPACTED SOIL IN LAST IMAGE	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7250595
716301561	ORIGINAL PHOTO TEMPLATE	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7250596
716301562	ORIGINAL INSPECTION	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7250597